



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: MSIG Insurance (Singapore) Pte. Ltd
COMPANY NAME: MSIG Insurance (Singapore) Pte. Ltd
STREET ADDRESS: 4 Shenton Way, #21-01 SGX Centre Two
POSTAL CODE: Singapore 068807
PHONE: 6827 2888

DATE: 7/10/2022

REF: SNA9222X
VEHICLE NO.: SNA9222X
MAKE: BMW
MODEL: X5
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>LABOUR</u>						
1	TO REMOVE & REFIT ALL LIGHTING & WIRING	1		\$100.00	\$ 100.00	40.	\$ 100.00
2	TO REMOVE & REFIT REVERSE SENSORS	1		\$200.00	\$ 200.00	40.	\$ 200.00
3	TO REMOVE & REFIT REAR WINDSCREEN	1		\$200.00	\$ 200.00	X un	\$ 200.00
4	TO REMOVE & REFIT EXHAUST PIPE & REALIGN	1		\$280.00	\$ 280.00	X un	\$ 280.00
5	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY AND REALIGN	1		\$1,000.00	\$ 1,000.00	600	\$ 1,000.00
6	TO PROVIDE SKILL LABOUR TO PAINT ALL NEW PARTS & PANELS	1		\$1,000.00	\$ 1,000.00	600	\$ 1,000.00
	<u>PARTS</u>					1280	
1	TAIL GATE	1		\$6,160.55	\$ 6,160.55	X un	\$ 6,160.55
2	TAIL GATE UPPER PROTECTOR	1		\$330.50	\$ 330.50	X un	\$ 330.50
3	TAIL GATE LOWER PROTECTOR <i>for gate</i>	1		\$253.30	\$ 253.30	bt-	\$ 253.30
4	TAIL GATE REFLECTOR LH & RH	1		\$65.60	\$ 65.60	X un	\$ 65.60
5	TAIL GATE LOGO	1		\$95.85	\$ 95.85	rel-	\$ 95.85
6	TAIL GATE X5 LOGO	1		\$65.60	\$ 65.60	rel-	\$ 65.60
7	REAR BUMPER	1		\$1,980.90	\$ 1,980.90	de-	\$ 1472 1,980.90
8	REAR BUMPER CLIPS	10		\$3.00	\$ 30.00	rel-	\$ 30.00
9	REAR BUMPER SIDE RETAINER LH & RH	2		\$152.80	\$ 305.60	X un	\$ 305.60
10	REAR BUMPER TOWING COVER	1		\$63.95	\$ 63.95	7 un	\$ 63.95
11	REAR BUMPER CENTRE PROTECTOR	1		\$347.50	\$ 347.50	de-	\$ 347.50
12	REAR BUMPER SIDE PROTECTOR LH & RH	2		\$167.40	\$ 334.80	X un	\$ 334.80

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
13	REVERSE SENSORS	2	236	\$463.90	\$ 1,855.60	nm —	\$ 472 1,855.60
14	REAR BUMPER REINFORCEMENT	1		\$948.20	\$ 948.20	21 —	\$ 707 948.20
15	REAR BUMPER REFLECTOR LH & RH	2		\$65.60	\$ 131.20	x nm	\$ 131.20
16	REAR END PANEL	1		\$1,194.90	\$ 1,194.90	Rp	\$ 1,194.90
17	REAR END PANEL TOP GARNISH	1		\$329.20	\$ 329.20	x nm	\$ 329.20
18	TAIL GATE INNER LOCK	1		\$288.35	\$ 288.35	x nm	\$ 288.35
19	TAIL GATE WEATHERSTRIP	1		\$226.10	\$ 226.10	7 nm	\$ 226.10
20	REAR EXHAUST PIPE	1		\$2,698.60	\$ 2,698.60	x nm	\$ 2,698.60
21	SEALANT	1		\$60.00	\$ 60.00	8 nm	\$ 60.00
SUBTOTAL					\$ 20,546.30	SUBTOTAL	\$ 20,546.30
GST 7%					\$ 1,438.24	GST 7%	\$ 1,438.24
TOTAL					\$ 21,984.54	TOTAL	\$ 21,984.54

3443.25

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)



Tamplin 97495747/6256356 1
 12/40/22 @ 415pm
 P/p Resny before paint
 tamplin@lkhauto.com
 5 days


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

SUPPLEMENTARY QUOTATION

QUOTATION FOR

NAME: MSIG Insurance (Singapore) Pte. Ltd
COMPANY NAME: MSIG Insurance (Singapore) Pte. Ltd
STREET ADDRESS: 4 Shenton Way, #21-01 SGX Centre Two
POSTAL CODE: Singapore 068807
PHONE: 6827 2888

DATE: 14/10/2022

REF: SNA9222X
VEHICLE NO.: SNA9222X
MAKE: BMW
MODEL: X5
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>PARTS</u>						
1	REAR BUMPER BRACKET	1		\$253.70	\$ 253.70	bt✓	\$ 253.70
2	REVERSE SENSOR WIRING	1		\$132.30	\$ 132.30	cut✓	\$ 132.30
3	TAILGATE CONTROL UNIT F005V00833	1		\$605.20	\$ 605.20	nw✓	\$ 605.20
4	TAILGATE LOWER PANEL	1		\$2,420.30	\$ 2,420.30	bt✓	\$ 2,420.30
	<u>LABOUR</u>						3411.50
1	TO DO DIAGNOSTIC & REPROGRAM TAILGATE SYSTEM	1		\$280.00	\$280.00		\$ 150 280.00
SUBTOTAL					\$ 3,691.50	SUBTOTAL	\$ 3,691.50
GST 7%					\$ 258.41	GST 7%	\$ 258.41
TOTAL					\$ 3,949.91	TOTAL	\$ 3,949.91

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)



3443.25
3411.50
6854.75
10% - 6169.27
6169.27
1280
150
7599.27
41586050, 05 days