

Vehicle Damage Assessment Report for [SLE6164C]

Estimate Created: 11/10/2022 09:48 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 18/05/2023 15:54 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Corolla
Engine Type			
License Plate Number	SLE6164C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$6,500.00 WITH 7 WORKING
DAYS

Insurlogic 4 (18/05/2023 15:54)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
LH front door		1	1270.80	-25.00 %	953.10
LH front door lock		1	374.50	-25.00 %	280.88
LH front door weatherstrip		1	230.10	-25.00 %	172.58
LH front door handle		1	189.40	-25.00 %	142.05
LH front door handle end piece		1	38.50	-25.00 %	28.88
LH front door inner trim board		1	681.40	-25.00 %	511.05
LH front door glass outer chrome moulding		1	168.10	-25.00 %	126.08
LH front door glass regulator gear		1	291.70	-25.00 %	218.78
LH front door glass regulator motor		1	545.10	-25.00 %	408.83
LH rocker panel		1	856.90	-25.00 %	642.68
Center pillar		1	699.10	-25.00 %	524.33
LH rear door		1	1255.90	-25.00 %	941.93
LH rear door inner trim door board		1	634.10	-25.00 %	475.58
LH rear door hinges		2	75.20	-25.00 %	112.80

Parts Subtotal 5,539.55

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
LH front door inner trim board clips		1.0	30.00	0.00 %	30.00
LH front door black trim		1.0	60.00	0.00 %	60.00
LH rear door inner trim board clips		1.0	30.00	0.00 %	30.00
LH rear door black trim		1.0	60.00	0.00 %	60.00

Materials Subtotal 180.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	1200.00	0.00 %	1,200.00
Check wiring	RnR	30.00	0.00 %	30.00
To apply tuff coat	RnR	80.00	0.00 %	80.00
To remove upholstery	RnR	40.00	0.00 %	40.00

To transfer front and rear door fttings.	RnR	160.00	0.00 %	160.00
--	-----	--------	--------	--------

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	900.00	0.00 %	900.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	1,510.00
			Paint Labor Subtotal	900.00
			Labor Subtotal	2,410.00

Summary

Repair Cost	8,129.55
Discount(20 %)	(1,625.90)
	6,503.65
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	6,503.65