



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel. 6844 1184

TP Grab

Xiao Tong

Vehicle No. SLE6164C

TOYOTA ALTIS

MR053REH104556124

QTY		DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT	
		PARTS (LIST ITEMS)					
1	FRONT LH DOOR	<i>Distorted.</i>			1270.80		✓
2	FRONT LH DOOR LOCK	<i>Jammed</i>			374.50		✓
3	FRONT LH DOOR WEATHERSTRIPE	<i>cut</i>			230.10		✓
4	FRONT LH DOOR HANDLE	<i>Brnd</i>			189.40		✓
5	FRONT LH DOOR HANDLE END PIECE	<i>Brnd</i>			38.50		✓
6	FRONT LH DOOR INNER TRIM BOARD	<i>cracked</i>			681.40		✓
7	FRONT LH DOOR GLASS OUTER CHROME MOULDING	<i>Brst</i>			168.10		✓
8	FRONT LH DOOR GLASS REGULATOR GEAR	<i>Brnd</i>			291.70		✓
* 9	FRONT LH DOOR GLASS REGULATOR MOTOR	<i>Damaged</i>			545.10		✓
10	FRONT LH DOOR WING MIRROR	<i>New</i>			1168.20		+
11	FRONT LH DOOR WING MIRROR COVER	<i>Pyris</i>			118.50		+
12	ROCKER PANEL LH	<i>Dented</i>			856.90		✓
13	CENTRE PILLAR	<i>Dented</i>			699.10		✓
14	CENTRE PILLAR INNER TRIM COVER (LOWER)	<i>New</i>			345.20		+
15	REAR LH DOOR	<i>Dented</i>			1255.90		✓
16	REAR LH DOOR LOCK	<i>New</i>			361.70		+
17	REAR LH DOOR WEATHERSTRIPE	<i>New</i>			224.60		+
18	REAR LH DOOR INNER TRIM DOOR BOARD	<i>cracked</i>			634.10		✓
19	REAR LH DOOR HINGE @75.20	<i>Brst</i>			150.40		✓
20	REAR LH DOOR CHECK	<i>New</i>			68.90		+
					9673.10		
				25%	2418.28	25%	
					7254.83		
		SPECIAL NETT ITEMS					
1	FRONT LH DOOR INNER TRIM BOARD CLIPS	<i>New</i>			30.00		✓
2	FRONT LH DOOR BLACK TRIM	<i>New</i>			100.00		60.
3	CENTRE PILLAR INNER TRIM COVER (LOWER) CLIPS	<i>New</i>			30.00		+
4	REAR LH DOOR INNER TRIM BOARD CLIPS	<i>New</i>			30.00		✓
5	REAR LH DOOR BLACK TRIM	<i>New</i>			100.00		60.
6	ROCKER PANEL SEALANT	<i>3 not new</i>			100.00		+
7	CENTRE PILLAR SEALANT				100.00		+
			Total Parts		490.00		



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Vehicle No. SLE6164C

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	PANEL BEATING	1600.00	1200.
2	SPRAY PAINTING	1400.00	900.
3	WIRING	100.00	30
4	TO APPLY TUFF COAT	150.00	80.
5	TO REMOVE UPHOLSTERY	150.00	40
6	TO TRANSFER FRONT & REAR DOOR FITTINGS	300.00	160.
	Labour Total :	3700.00	
	TOTAL (PARTS & LABOUR):	11444.83	

total: 8129.50

h/s: 6.5K.

07 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6.5K.