



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG #01-01/02
BUKIT MERAH ENTERPRISE CENTRE,
SINGAPORE 159410

TEL : 6235 1311

FAX : 6235 5256

ATTN :

YOUR REF NO : SNC8287E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 03/10/2022

TP VEH REG NO : SNC8287E

ESTIMATE

NO : QUOT202210-000011(00)

DATE : 10/10/2022

POLICY NO : SD22V05556/VPZ/R09

VEH REG NO : SBL6968G

MAKE/MODEL : MERCEDES BENZ E200 SEDAN
AVG (R18 LED)

CHASSIS NO : WDD2130802A751689

ENGINE NO : 26492080025373

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SBL6968G

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Front fender - RH	1	1,150.00	1,150.00
2 Front bumper	1	1,975.00	1,975.00
3 Front bumper side retainer RH	1	24.00	24.00
4 Front bumper sensor	1	215.00	215.00
5 Front bumper sensor seal	1	12.00	72.00
6 Headlamp RH	1	3,890.00	3,890.00
7 Sport Rim RH	1	740.00	740.00
			8,066.00
		Less 10%	806.60
			7,259.40
LABOUR			
8 To remove and refit front bumper sensor	1	80.00	80.00
9 To panel beat and straighten front chassis frame, to cut and weld front RH fender, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00
10 To putty and spray paint on affected areas	1	1,000.00	1,000.00
11 To check and rectify wiring system	1	80.00	80.00
12 To check wheel alignment by computerised	1	180.00	180.00
13 To re-program front headlamp	1	350.00	350.00
			2,590.00

TOTAL S\$ 9,849.40

ADD GST @ 7% 689.46

GRAND TOTAL S\$ 10,538.86

SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED THIRTY EIGHT AND CENTS EIGHTY-SIX ONLY

LKK Auto Consultants hence notify

the Repairer of the following:

To resurvey before and after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE