

ASS. REC. BY:

Kenneth

REF:

CT21 220100261kv

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SBL 6386

Yr Regn:

02, 20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mw 5200

c.c.

1991

Colour

M: Black

A/C:

Insured / Std / NI / NA

Sp. Reading

37282

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2130802A 751689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

245/43R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

3/10/22

D.O.I.

12/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS, SI

Fixings

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG #01-01/02
BUKIT MERAH ENTERPRISE CENTRE,
SINGAPORE 159410

TEL : 6235 1311

FAX : 6235 5256

ATTN :

YOUR REF NO : SNC8287E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 03/10/2022

TP VEH REG NO : SNC8287E

ESTIMATE

NO : QUOT202210-000011(00)

DATE : 10/10/2022

POLICY NO : SD22V05556/VPZ/R09

VEH REG NO : SBL6968G

MAKE/MODEL : MERCEDES BENZ E200 SEDAN
AVG (R18 LED)

CHASSIS NO : WDD2130802A751689

ENGINE NO : 26492080025373

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SBL6968G

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Front fender - RH	1	1,150.00	1,150.00 ✓
2 Front bumper	1	1,975.00	1,975.00 ?
3 Front bumper side retainer RH	1	24.00	24.00 ?
4 Front bumper sensor	1	215.00	215.00 ✓
5 Front bumper sensor seal	6	12.00	72.00 ?
6 Headlamp RH	1	3,890.00	3,890.00 ?
7 Sport Rim RH	1	740.00	740.00 ✓
			8,066.00
		Less 10%	806.60
			7,259.40
LABOUR			
8 To remove and refit front bumper sensor	1	80.00	80.00 ?
9 To panel beat and straighten front chassis frame, to cut and weld front RH fender, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00 400
10 To putty and spray paint on affected areas	1	1,000.00	1,000.00 440
11 To check and rectify wiring system	1	80.00	80.00 20
12 To check wheel alignment by computerised	1	180.00	180.00 80
13 To re-program front headlamp	1	350.00	350.00 ?
			2,590.00
TOTAL			S\$ 9,849.40
ADD GST @ 7%			689.46
GRAND TOTAL			S\$ 10,538.86

SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED THIRTY-EIGHT AND CENTS EIGHTY-SIX ONLY

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/10/2022 19:09 (SGT)
Reported by	Both
Date of Accident	03/10/2022 22:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	COLLYER QUAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBL6968G
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	RMG RENT-A-CAR PTE LTD
Company Reg No	199100384R
Email Address	VINCENT@RMGRENTACAR.COM.SG
Mobile Phone No	(Phone) +65-97509672
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E220
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD22V05556/VPZ/R09

DRIVER

Name of Driver	DU JING
Passport No/FIN	G3071636T
Date Of Birth	01/03/1973
Occupation	Indoor

IMPORTANT NOTICE

- I understand, acknowledge, agree and consent that

(c) my Personal Information may can be disclosed by any of the Members and/or GFA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

