



Case Details

Case Reference Number : TAX/10/22/2021
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1308B

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19576-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 06/10/2022 09:30 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FENDER ASM-FRT-RH	1	379.81	379.81	10.00	341.83	Replace	0	0	Not Give	X11
Standard	Main			DOOR ASM-FRT SI - RH	1	2,338.44	2,338.44	10.00	2,104.60	Replace	1	0	Repair	R
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	nee /
Standard	Main			DOOR ASM-RR SI -RH	1	2,185.04	2,185.04	10.00	1,966.54	Replace	1	0	Repair	R
Standard	Main			PANEL-BODY SI OTR - RH	1	1,434.89	1,434.89	10.00	1,291.40	Replace	1	0	Repair	R
Standard	Main			STICKER ELECTRIC (LOGO	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	nee /
Standard	Main			MIRROR ASM-O/S RR VIEW - RH	1	478.40	478.40	10.00	430.56	Replace	0	0	Not Give	X11
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	0	Repair	R
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	0	0	Not Give	X11
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	0	0	Not Give	X11
Standard	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	0	0	Not Give	X11
Standard	Main			LAMP ASM-RR FOG - RH	1	189.07	189.07	10.00	170.16	Replace	0	0	Not Give	X11

Total Spare Part Cost 10,311.81
 Lump Sum Discount (%) 0.00
 Final Spare Part Cost 10,311.81

Surveyor Total 81.60
 Lump Sum Dis (%) 0
 Final Sur Total 81.60

10/11/22, 4:07 PM

Surveyor Approval

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BEARING ASM-RR WHL	1	335.40	335.40	10.00	301.86	Replace	0	0	Not Give	X11
Standard	Main			BEAM ASM-RR SUSP EQLZR	1	1,649.54	1,649.54	10.00	1,484.59	Replace	0	0	Not Give	X11
Standard	Main			WHEEL	1	618.07	618.07	10.00	556.26	Replace	1	0	Repair	R
Total Spare Part Cost									10,311.81	Surveyor Total		81.60		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									10,311.81	Final Sur Total		81.60		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	3,000.00	500.00	
Total:			3,000.00	500.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	0	X11
2	Main	TO RESPRAY FRONT FENDER RH	428.00	0	X11
3	Main	TO RESPRAY FRONT DOOR RH	428.00	220	
4	Main	TO RESPRAY VIEW MIRROR	230.00	0	X11
5	Main	TO RESPRAY SILL MEMBER LH	230.00	0	X11
6	Main	TO RESPRAY RH REAR DOOR	428.00	220	
7	Main	TO RESPRAY REAR FENDER RH	428.00	220	
8	Main	TO RESPRAY REAR BUMPER	428.00	220	
9	Main	TO RESPRAY RIM	230.00	50	
Total:			3,258.00	930.00	✓

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,369.00	360.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X ₁₁	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 X ₁₁	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 X ₁₁	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
5	Main	TO TRANSFER DOOR MECHANISM	240.00	0 X ₁₁	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 X ₁₁	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0 X ₁₁	
8	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00	
9	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			1,360.00	360.00 /	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	10,311.81	81.60
Total Labour Cost	3,000.00	500.00
Total Spray Painting	3,258.00	930.00
Other	1,360.00	360.00
Overall Total	17,929.81	1,871.60
Lump Sum Repair Option		☐
Lump Sum Total	0.00	1,871.60
Surveyor Approved Amount		1,871.60
No of Repair Days*	10	5


Remarks

After repair photo FOR CHECK ITEM and REPLACE ITEM
PLEASE CALL SURVEYOR RASUL / HP : 9001 0068, email: rasul@lkkauto.com.sg

Surveyor Name

Rasul

Signature



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear