

10/11/22, 3:40 PM

Repairer Estimates


PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd
 (Co. Reg. No. 201006949C)
 Blk 3022A Ubi Road 1 #01-45/46 S408716
 T: +65 6741 5336 | F: +65 6741 7208
 E: claims@procarcare.com.sg
 W: www.procarcare.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1022-8706
Policy No:	MPC22B00020200	Date of Loss:	09/10/2022
Vehicle Reg. No.:	8LD6228H	Driveable?	
Driver Age/Info:	44 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YAP SOON KONG (YE SHUNQIANG)	Contact No:	+6590288243
Driver:	TAN HWEE SHAN (CHEN HUI SHAN)		
Make/Model:	HYUNDAI TUCSON, 2.0 TL (A)	Vehicle Reg. Date:	24/06/2016
Vehicle Colour:	RED	Chassis No:	KMHJ3813MHU253692
Engine No:	G4NAGU212763		
Odometer:	89556 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	9,823.80
Labour	845.00
Paintwork Labour	1,380.00
Towing	600.00
	0.00
Gross Total (S\$)	12,158.80
+ GST 7.00% (S\$)	851.12
Nett Amount (S\$)	13,010.02

This claim is handled by: LIANG SIEW CHIN

Generated using Meritman e-Claims Internet Estimation & Adjusting System

not Authorized
 dell
 meromj
 12/10/22
 Excess?
 4 days
 P/P 9

10/11/22, 3:40 PM

Repair Estimates

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Oct 2022)
 Parts: N/A HYUNDAI TUCSON 2.0 TL (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Car Care Pte Ltd/SLD6228H/11/10/2022 15:40
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/Values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2	NA	*FRONT ABSORBER - LH/RH			
2	2	NA	*FRONT ABSORBER TOP MTO- LH/RH	0.00	0.00	*520.00 F
3	2	NA	*FRONT LOWER ARM WITH BALL JOINT- LH/RH	0.00	0.00	*110.00 F
4	2	NA	*FRONT KNUCKLE ARM - LH/RH	0.00	0.00	*370.00 F
5	2	NA	*FRONT KNUCKLE ARM BEARING - LH/RH	0.00	0.00	*390.00 F
6	1	NA	*FRONT CROSSMEMBER	0.00	0.00	*370.00 F
7	1	NA	*FRONT STAY LINK - LH	0.00	0.00	*1,050.00 F
8	1	NA	*FRONT TIE ROD END; OUTER - LH	0.00	0.00	*48.00 F
9	2	NA	*FRONT RIM - LH/RH	0.00	0.00	*46.00 F
10	1	NA	*FRONT BUMPER	0.00	0.00	*1,560.00 F
11	10	NA	*FRONT BUMPER CLIPS	0.00	0.00	*350.00 F
12	1	NA	*FRONT BUMPER LOWER GARNISH	0.00	0.00	*18.00 F
13	4	NA	*FRONT BUMPER SENSOR	0.00	0.00	*230.00 F
14	1	NA	*FRONT BUMPER SENSOR WIRE	0.00	0.00	*360.00 F
15	1	NA	*GRILLE WITH CHROME ASSY & LOGO ASSY	0.00	0.00	*110.00 F
16	1	NA	*FRONT BUMPER FOG LAMP COVER - LH	0.00	0.00	*550.00 F
17	1	NA	*FRONT BUMPER DAYLIGHT - LH	0.00	0.00	*20.00 F
18	1	NA	*FRONT BUMPER FOG LAMP - LH	0.00	0.00	*185.00 F
19	1	NA	*FRONT BUMPER REINFORCEMENT	0.00	0.00	*320.00 F
20	1	NA	*FRONT BUMPER FOAM	0.00	0.00	*85.00 F
21	1	NA	*FRONT BUMPER CENTER LOWER GRILLE	0.00	0.00	*75.00 F
22	1	NA	*HEAD LAMP - LH	0.00	0.00	*1,250.00 F
23	1	NA	*SUPPORT PANEL ASSY	0.00	0.00	*480.00 F
24	1	NA	*SUPPORT PANEL TOP GARNISH	0.00	0.00	*30.00 F
25	4	NA	*SUPPORT PANEL TOP GARNISH CLIPS	0.00	0.00	*8.00 F
26	1	NA	*FRONT BUMPER UNDER COVER ENGINE	0.00	0.00	*220.00 F

F=Franchise part.

Sub Total (\$\$) 8,740.00
 + Margin on L,N Items 10.00% (\$\$) 874.90
 Total Parts (\$\$) 9,623.90

Progressive Car Care Pte Ltd/SLD6228H/11/10/2022 15:40, Not valid without Reference section.
 Generated using Meritman e-Claims IEAS

10/11/22, 3:40 PM

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	
2	1	FRONT NUMBER PLATE WITH CASING	60.00
3	2	FRONT TYRE - LH/RH	35.00
			560.00
Sub Total (\$)			645.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	300 600.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	300 600.00
3	TO CHECK WIRING	New	20 50.00
4	TO 4 WHEEL ALIGNMENT	New	60 70.00
5	TO REMOVE; REPLACE FRONT CROSSMEMBER; FRONT BOTH UNDERCARRIAGE	New	300 800.00
6	TO 4 WHEEL ALIGNMENT	New	300 70.00
Gross Labour Cost (\$)			1,890.00

Progressive Car Care Pte Ltd/SLD6228H/11/10/2022 18:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK II repair bench, draw signor and the support dolly system to provide accurate re-alignment and speedy repairs.