

FW 929R.

TP Sampo

Hyundai Elantra

Veron.

KM1HD841CMJU740359

Rear Bumper Distorted

495.40 ✓

Rear Bumper Clips. μ

30(SN) ✓

Rear Bumper Side Holder x 02

Dmgd $38.2 \times 2 = 76.40$ ✓

Rear Bumper Lower Spoiler

Distorted ~~1000(SN)~~ 750(SN)

Rear Bumper Reinforcement.

Distorted 329.60 ✓

Rear Bumper Reinforcement Stay x 02.

μ $95.6 \times 2 = 191.20$ ✓

Rear Bumper Reinforcement Bracket x 05.

Dmgd $18 \times 5 = 90$ ✓

Rear Bumper Reflector x 02 μ

$72.5 \times 2 = 145$ ✓

Reverse Sensor Dmgd

~~280(SN)~~ 200(SN)

Taillamp x 02 And

$598 \times 2 = 1196$ ✓

Bootlid Dented

1782.10 ✓

Bootlid Lock Dmgd

166.70 ✓

Bootlid Weatherstripe, Cut

152.60 ✓

EW 929 R.

Bootlid Inner Trim Cover	} ne n	179.80 +
Bootlid Inner Trim Cover Clips.		30(SN) +
Bootlid Lamp x 02	} ne n	450.2 x 2 = 900.40 +
Bootlid Hinge x 02		94.3 x 2 = 188.60 +
Hyundai Logo.	} ne n	59.60 ✓
Elantra Wording.		60.90 ✓
S Emblem.		54.10 ✓
Spare Tyre Panel Top Board.		ne n 266.80 +
Rear Fender Inner Trim Board x 02	} ne n	343.4 x 2 = 686.80 +
Rear Fender Inner Trim Board Clips.		60(SN) +
Rear Camera.	ne n	480(SN) +
Rear End Panel	Dented	569.40 ✓
Rear End Panel Sealant.	ne n	60(SN) ✓
Rear End Panel Top Garnish.	Dented	142.30 ✓
Rear End Panel Top Garnish clips.	ne n	20(SN) ✓
Rear Antenna Sensor	Dented	178.50 ✓

EW 929 R.

Panel Beating

Spray Painting

Wiring

To remove reverse sensor

To remove rear camera.

To remove upholstery.

To spray diff coat.

To transfer bootlid fittings.

List. 446340

len 20%: 357072

S.N 1060

Labour: 2130

~~1200~~ 800

~~1200~~ 1000

~~50~~ 30

~~100~~ 50

2110 ~~100~~ 50

~~150~~ 60

~~150~~ 80

~~150~~ 60

total: 6760.72

4/s: ~~54K~~
5900

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

D...