



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SLC8421H (CK)**

Your Ref: **SMB3593X**

Date: **8-Oct-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Email : motor_claims@first-insurance.com.sg

First Capital Insurance Limited

6 Raffles Quay #21-00
Singapore 048580

Assessed Vehicle No : **SLC8421H**
Car Make and Model : **HYUNDAI ELANTRA AD 1.6 GLS AT**
Date of Accident : **27-Sep-22**
Date of Assessment : **8-Oct-22**

We have carried out a physical assessment of SMW268U at our workshop Auto Insure Pte Ltd sustained damages to the FRONT RH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **L/S**
Adjusted Amount : **\$ 3,062.34**
Est. Repair Days : **3**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: **SLC8421H**

Your Ref: **SMB3593X**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	FRONT BUMPER <i>repair</i>		\$ 1,050.00
2	1	FRONT BUMPER SIDE RETAINER RH <i>X nn</i>		\$ 40.00
3	1	FOG LAMP COVER RH <i>cm</i>		\$ 155.00
4	1	FRONT FOG LAMP RH <i>X nn</i>		\$ 295.00
5	1	FRONT BUMPER LAMP RH <i>X nn</i>		\$ 225.00
6	1	FRONT TOWNG COVER <i>X nn</i>		\$ 25.00
			SUB TOTAL	\$ 1,790.00
			LESS 20%	\$ 358.00
			TOTAL AMOUNT	\$ 1,432.00

Our Ref: **SLC8421H**

Your Ref: **SMB3593X**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS <i>X nn</i>		\$ 50.00
			SUB TOTAL	\$ 50.00
			TOTAL PARTS COST	\$ 1,482.00

155
206
124

Our Ref: **SLC8421H**

Your Ref: **SMB3593X**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 200 600.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ X 100.00
3	TO REMOVE & REFIT FRONT BUMPER PARKING SENSORS	\$ X 80.00
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 200 400.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ X 40.00
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ X 50.00
7	TO VACUUM, WAXING & CLEAN	\$ X 60.00
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ X 50.00
TOTAL BEFORE GST		\$ 2,862.00
GST 7%		\$ 200.34
TOTAL (PARTS & LABOUR):		\$ 3,062.34

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 3,062.34** for part by part with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Handwritten notes:
Rahul
Hp 90010068
1 1/2 days
P/P
11/10/22 @ 1635
Resy after repair
Resy old & new part

Handwritten calculations:
124
400
524