

Vehicle Damage Assessment Report for [SJH8619C]

Estimate Created: 11/10/2022 10:34 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 28/12/2022 08:53 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Jazz
Engine Type			
License Plate Number	SJH8619C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$4,000.00 WITH 7 DAYS

Insurlogic 5 (28/12/2022 08:52)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
LH SIDE MIRROR ASSY		1	503.20	-20.00 %	402.56
FRONT LH DOOR		1	964.50	-20.00 %	771.60
FRONT LH DOOR STICKER		1	53.40	-20.00 %	42.72
FRONT LH WINDOW GLASS		1	282.20	-20.00 %	225.76
FRONT LH DOOR OUTER GARNISH MOULDING @ WINDOW GLASS		1	69.60	-20.00 %	55.68
FRONT LH DOOR HANDLER		1	106.80	-20.00 %	85.44
REAR LH DOOR		1	896.30	-20.00 %	717.04
REAR LH DOOR STICKER		1	55.50	-20.00 %	44.40
REAR LH DOOR OUTER GARNISH MOULDING @ WINDOW GLASS		1	59.80	-20.00 %	47.84
REAR LH FENDER		1	753.70	-20.00 %	602.96
LH TAILLAMP		1	350.40	-20.00 %	280.32

Parts Subtotal 3,276.32

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT LH DOOR RUBBER		1.0	50.00	0.00 %	50.00
FRONT LH INNER DOOR COMPARTMENT CLIPS		1.0	50.00	0.00 %	50.00

Materials Subtotal 100.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
LABOUR REMOVE/REFIX ACCIDENT DAMAGED PARTS. TO KNOCK, JACK, CUT, WELD & REALIGN ACCIDENT AFFECTED AREA	RnR	800.00	0.00 %	800.00
TO CHECK WIRING SYSTEM	RnR	20.00	0.00 %	20.00
TO APPLY ANTI RUST TREATMENT	RnR	90.00	0.00 %	90.00

TO REMOVE/REFIX FRONT LH WINDOW GLASS, MECHANISM& ETC TO NEW DOOR	RnR	60.00	0.00 %	60.00
TO REMOVE/REFIX REAR LH WINDOW GLASS, MECHANISM& ETC TO NEW DOOR	RnR	60.00	0.00 %	60.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINT ON ALL AFFECTED AREA	Full spray	680.00	0.00 %	680.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	1,030.00
			Paint Labor Subtotal	680.00
			Labor Subtotal	1,710.00

Summary

Repair Cost	5,086.32
Discount(20 %)	(1,017.26)
	4,069.06
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,069.06