



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22010037/Uqy3q2	
			Date: 27/10/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 3939X	Veh. Inspected	SMP 2696R	
Policy No.	D22099240	Coverage (\$)	0.00	
Claim No.	D22003166MFCV	Excess (\$)	0.00	
Assign From	AINI BINTE	Assign Date	11/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72006103	Colour	WHITE	
Odometer	109248 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	6 mm	
L/H Front Tyre	185/60 R15	MICHELIN	6 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	6 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/10/2022	Inspection Date	12/10/2022	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	