



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS3/UOI22004061/Tvy3e2-1	
			Date: 01/11/2022	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLR 9750Y	Veh. Inspected	SVJ 3308J	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D15112205	Excess (\$)	0.00	
Assign From	KATIE LEE	Assign Date	11/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ B180	c.c	1332	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	W1K2470842J120695	Colour	SILVER	
Odometer	12977 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/04/2022	Inspection Date	29/04/2022	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	