

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA1401U

Make : HYUNDAI

Model : IONIQ(G3)

Date: 10.10.2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>X</i>			\$459.40
10	REAR BUMPER CLIPS <i>X</i>			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY <i>X</i>			\$451.25
1	REAR BUMPER REINFORCEMENT <i>X</i>			\$394.80
1	REAR BUMPER TOWING COVER <i>X</i>			\$98.80
1	REAR BUMPER REINFORCEMENT BRACKET LH <i>X</i>			\$138.10
SUB TOTAL				\$1,564.35
LESS 20%				\$312.87
DISCOUNTED TOTAL				\$1,251.48
REAR BUMPER RUBBER MAT <i>X</i>				\$50.00
REAR BUMPER REVERSE SENSOR <i>X</i>				\$180.00
				-10%
				\$230.00
Labour Charge				
PANEL BEATING				\$400.00
SPRAY PAINTING CHARGE				\$300.00
CHECK ALL LIGHTING				\$60.00
REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR				\$840.00
ESTIMATE TOTAL				\$2,321.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2D mfs
6mo Bf
10/10
2 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts price to be confirmed on "Prejudice" basis
- Third party to be confirmed
- No illegal work to be performed
- Supplier to be confirmed and resurveyed and is subject to confirmation from Insurance Company

Acknowledged: _____
Signed: _____
Date: _____

640