## **COMFORT TRANSPORTATION PTE LTD**

## REPAIR ESTIMATE

Vehicle No.: SHA8755C

Make : HYUNDAI Model : I-40 Date: 10/10/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amou	int
	REAR BUMPER COVER / CAA			\$ 5	53.00
1	REAR BUMPER CLIPS			\$	22.00
1	REAR BUMPER LOWER COVER X			\$ 2	28.00
1	REAR BUMPER REINFORCEMENT			\$ 4	28.40
	SUB TOTAL			\$ 1,2	31.40
	LESS 20%			\$ 2	46.28
	DISCOUNTED TOTAL			\$ 9	85.12
	REAR BUMPER REVERSE SENSOR X			\$ 1	<b>35</b> .70
				\$ 1	35.70
	Labour Charge				
	PANEL BEATING			\$ 30	00.00
	SPRAY PAINTING CHARGE			\$ 30	00.00
	REMOVE/REFIX REVERSE SENSOR			\$	0.00
	TOTAL LABOUR			\$ 60	<b>60.00</b>
	ESTIMATE TOTAL			\$ 1.78	30.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Pays. 45 600 Ex (o) 10 2 pm

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are sufficient of confirmation

• Third party surve

• Without Prejudice\* basis

• No illegal me

• Suppleme

• Is subject to the confirmation

• Acknowledged of places and surveyed and is subject to the confirmation

Acknowledged of places and surveyed and sis subject to the confirmation

• Third party surve

• Acknowledged of places and surveyed and is subject to the confirmation

• Third party surve

• Acknowledged of places and surveyed and is subject to the confirmation of the confirmat