

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS22010047/KWY3M4**Date:** 21/10/2022**REFERENCE**

Insured/Claimant:	BIS MOTORING PTE LTD	Policy No:	SP2002451400
Date of Loss:	09/10/2022	Nature of Claim:	OD
		Claim No:	202222007354

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK2413S	Engine No:	A2183178JSUX0330
Make & Model:	OPEL INSIGNIA GRANDSPORT, 1.6 (A)	Chassis No:	W0VZM6EF3K1034528
Reg. Date:	01/04/2019 (Man. Year: 2019)	Odometer:	237785 km
Colour:	Metallic Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Farroad 9 mm	Rear Left Side:	Grenlander 8 mm
Front Right Side:	Farroad 9 mm	Rear Right Side:	Grenlander 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,205.10	2,421.76	3,783.34	60.97
Miscellaneous Items	49.00	0.00	49.00	100.00
Labour	2,280.00	1,120.00	1,160.00	50.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,534.10	3,541.76	4,992.34	58.50
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	6,534.10	1,541.76	4,992.34	76.40
+ GST 7.00/7.00% (S\$)	457.39	107.92	349.47	76.41
Nett Amount (S\$)	6,991.49	1,649.68	5,341.81	76.40

INSPECTION

Date of Assignment:	11/10/2022 Present Location:	Munich Autocare Pte Ltd (HQ)
Date Inspected:	12/10/2022 Inspected At:	MUNICH AUTOCARE PTE LTD
Estimated Period of Repair:	5.0 days	60 JALAN LAM HUAT
		#07-43 CARROS CENTER, SINGAPORE 737869

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts: 143	OPEL INSIGNIA GRANDSPORT 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK2413S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	39196928	*Front Door RH (WCP)	Bent	2,129.00 F	*1,703.20 F
2	1	13531200	*FRONT DOOR HANDLE (WCP)	Serviceable	307.00 F	*- F
3	1	13533640	*FRONT DOOR INNER LOCK RH (WCP)	Repair	422.00 F	*- F
4	1	13583613	*FRONT DOOR HINGE UPPER RH (WCP)	Repair	44.00 F	*- F
5	1	13583618	*FRONT DOOR HINGE LOWER RH (WCP)	Repair	44.00 F	*- F
6	1	39185963	*FRONT DOOR CHECK RH (WCP)	Serviceable	97.00 F	*- F
7	1	39176501	*FRONT DOOR INNER TRIMBOARD RH (WCP)	Serviceable	784.00 F	*- F
8	1	39125440	*FRONT FENDER RH (WCP)	Bent	450.00 F	*477.60 F
9	1		*FRONT FENDER INNER SHIELD OUTER (WCP)	Serviceable	95.00 F	*- F
10	1	YQ00011480	*Front Fender Signal Lamp/Cover RH (WCP)	Broken	26.00 F	*20.80 F
11	1	39148126	*FRONT side mirror assy RH (WCP)	Serviceable	514.00 F	*- F
12	1	39081047	*Cover , mirror RH (WCP)	Serviceable	85.00 F	*- F
13	1	13343699	*Motor , mirror adjustment RH (WCP)	Serviceable	186.00 F	*- F
14	1	13312747	*Tyre rim - Alloy Rim (WCP)	Serviceable	458.00 F	*- F

F=Franchise part.

Sub Total (\$)	5,641.00	2,201.60
+ Margin on L,N Items 10.00/10.00% (\$)	564.10	220.16
Total Parts (\$)	6,205.10	2,421.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	7	FRONT FENDER INNERSHIELD CLIP SET (Not Necessary)	49.00	0.00
Sub Total (\$\$)			49.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION, WINDOW, SIDE MIRROR	New	80.00	20.00
2	TO REMOVE & REPLACE SIDE MIRROR & RIM	New	120.00	0.00
3	WHEEL ALIGNMENT	New	80.00	0.00
4	TO RESPRAY FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH,SIDE MIRROR RHAND ALL THE EFFECTED AREAS.	New	1,000.00	500.00
5	TO DISMANTLE ,KNOCKING, PANEL BEATING, REFIX FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH,AND ALL THE EFFECTED AREAS.	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,280.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >