

22, 5:10 PM

Repairer Estimates

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43
Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

LKK

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

| | | | |
|---------------------|----------------------|-----------------------|------------|
| Claim Type: | OD (OWN DAMAGE) | Ref. No: | |
| Policy No: | SP2002451400 | Date of Loss: | 09/10/2022 |
| Vehicle Reg. No.: | SMK2413S | Driveable? | |
| Driver Age/Info: | | Party At Fault: | UNKNOWN |
| TP Injury Involved? | NO | Third Party Involved? | YES |
| Insured/Claimant: | BIS MOTORING PTE LTD | | |

| | | | |
|-----------------|---|--------------------|-------------------|
| Make/Model: | OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 TURBO (A) | Vehicle Reg. Date: | 01/04/2019 |
| Vehicle Colour: | SILVER | | |
| Engine No: | A2183178JSUX0330 | Chassis No: | W0VZM6EF3K1034528 |
| Odometer: | 237784 KM | | |

| | |
|-------------------------------|-----|
| Paint Type: | |
| Total Loss? | NO |
| Est. Duration of Repair (day) | 5 ✓ |

83540.88

NOT Notwork
Primary B4 claim
Ex B2000

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

COST OF CLAIMS

| | Amount |
|------------------------------|----------|
| Parts | |
| Miscellaneous Items | 6,205.10 |
| Labour | 49.00 |
| Paintwork Labour | 2,280.00 |
| Towing | 0.00 |
| | 0.00 |
| Calculated Gross Total (S\$) | 8,534.10 |
| - Excess (S\$) | 2,000.00 |
| (S\$) | 6,534.10 |
| + GST 7.00% (S\$) | 457.39 |
| Nett Amount (S\$) | 6,991.49 |

This claim is handled by: LIM JIA HAW

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)
 Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | | %Disc | %Depr | Amount | |
|-----|-----|------------|------------------------------------|------------|-------|-------|-------------|---|
| 1 | 1 | 39196928 | *Front Door RH | \$1,705.20 | 0.00 | 0.00 | *2,129.00 F | ✓ |
| 2 | 1 | 13531200 | *FRONT DOOR HANDLE | | 0.00 | 0.00 | *307.00 F | ✓ |
| 3 | 1 | 13533640 | *FRONT DOOR INNER LOCK RH | | 0.00 | 0.00 | *422.00 F | ✓ |
| 4 | 1 | 13583613 | *FRONT DOOR HINGE UPPER RH | | 0.00 | 0.00 | *44.00 F | ✓ |
| 5 | 1 | 13583618 | *FRONT DOOR HINGE LOWER RH | | 0.00 | 0.00 | *44.00 F | ✓ |
| 6 | 1 | 39185963 | *FRONT DOOR CHECK RH | | 0.00 | 0.00 | *97.00 F | ✓ |
| 7 | 1 | 39176501 | *FRONT DOOR INNER TRIMBOARD RH | | 0.00 | 0.00 | *784.00 F | ✓ |
| 8 | 1 | 39125440 | *FRONT FENDER RH | \$477.60 | 0.00 | 0.00 | *450.00 F | ✓ |
| 9 | 1 | | *FRONT FENDER INNER SHIELD OUTER | | 0.00 | 0.00 | *95.00 F | ✓ |
| 10 | 1 | YQ00011480 | *Front Fender Signal Lamp/Cover RH | \$26.80 | 0.00 | 0.00 | *26.00 F | ✓ |
| 11 | 1 | 39148126 | *FRONT side mirror assy RH | | 0.00 | 0.00 | *514.00 F | ✓ |
| 12 | 1 | 39081047 | *Cover , mirror RH | | 0.00 | 0.00 | *85.00 F | ✓ |
| 13 | 1 | 13343699 | *Motor , mirror adjustment RH | | 0.00 | 0.00 | *186.00 F | ✓ |
| 14 | 1 | 13312747 | *Tyre rim - Alloy Rim | | 0.00 | 0.00 | *458.00 F | ✓ |

F=Franchise part.

Sub Total (S\$) 5,641.00
 + Margin on L,N Items 10.00% (S\$) 564.10
 Total Parts (S\$) 6,205.10

Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

2, 5:10 PM

Repairer Estimates

Estimates on Miscellaneous Items

| Qty | Particulars | Amount |
|----------------------------|-----------------------------------|-------------------|
| Miscellaneous Items | | |
| 7 | FRONT FENDER INNERSHIELD CLIP SET | <i>nn</i> 49.00 X |
| Sub Total (S\$) | | 49.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|--------------------------------|---|----------|----------------------|
| Labour Items | | | |
| 1 | TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION, WINDOW, SIDE MIRROR | New | <i>200</i> 80.00 |
| 2 | TO REMOVE & REPLACE SIDE MIRROR & RIM | New | <i>nn</i> 120.00 X |
| 3 | WHEEL ALIGNMENT | New | <i>nn</i> 80.00 X |
| 4 | TO RESPRAY FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH, SIDE MIRROR RH AND ALL THE EFFECTED AREAS. | New | <i>5000</i> 1,000.00 |
| 5 | TO DISMANTLE ,KNOCKING, PANEL BEATING, REFIX FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH, AND ALL THE EFFECTED AREAS. | New | <i>6000</i> 1,000.00 |
| Gross Labour Cost (S\$) | | | 2,280.00 |

Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >