

12:5:10 PM

Repairer Estimates

### Estimates on Miscellaneous Items

Qty Particulars

Amount

#### Miscellaneous Items

1 7 FRONT FENDER INNERSHIELD CLIP SET

*nn* 49.00 *X*

Sub Total (S\$) 49.00

### Estimates on Labour

No Particulars

Lab.Type Amount

#### Labour Items

- 1 TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION, WINDOW, SIDE MIRROR *2ol*
- 2 TO REMOVE & REPLACE SIDE MIRROR & RIM *nn* 80.00 *X*
- 3 WHEEL ALIGNMENT *nn* 120.00 *X*
- 4 TO RESPRAY FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH, SIDE MIRROR RH AND ALL THE EFFECTED AREAS. *5ool* 80.00 *X*
- 5 TO DISMANTLE ,KNOCKING, PANEL BEATING, REFIX FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH, AND ALL THE EFFECTED AREAS. *6ool* 1,000.00

Gross Labour Cost (S\$) 2,280.00

Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



To : MUNICH AUTOCARE PTE LTD  
 60 JALAN LAM HUAT  
 #02-02/03 CARROS CENTRE  
 Singapore 737869

Invoice No : CGI-ASC-22IR07010E  
 Invoice Date : 11/10/2022  
 Mileage (KM) :  
 Service Advisor : RAHIM  
 Credit Term : 30

Vehicle No :  
 Vehicle Model :

Parts Charges						
S/No	Parts Code	Description	Qty	Unit Price SGD	Discount SGD	Total Price SGD
1	39196928	RH FRONT DOOR PANEL 39122985->39128508->39138838->39148096->3917119	1.00	2,129.00	425.80	1,703.20
2	YQ00011480	LAMP, ASSY., SIDE REPEATER, RH	1.00	26.00	5.20	20.80

Please check the condition of this item. All bills are not eligible for any warranty and are non-refundable.  
 non-échangeable.

Remark : SMK2413S INSIGNIA GS 1.6D

SUB-TOTAL : 1,724.00  
 ADD 7.00% GST : 120.68  
 TOTAL WITH GST AMOUNT : 1,844.68



Corporate PayNow / UEN No: 199601763M  
 Bank Transfer: DBS Current Account No (003-916922-1)  
 Please indicate Tax Invoice No [22IR07010E] as Payment Reference or Remarks

This is a computer generated invoice. No signature is required.

No condition of any warranty and are non-refundable.

Remark : SMK2413S INSIGNIA GS 1.6D  
 E & O E

Advisor : RAHIM  
 Term : 30  
 Qty : 1.00  
 Unit Price SGD : 597.00  
 Discount SGD : 119.40

22, 5:10 PM

Repairer Estimates

LKK

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)  
60 Jalan Lam Huat, #07-43  
Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@municautocare.com.sg

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	09/10/2022
Vehicle Reg. No.:	SMK2413S	Driveable?	
Driver Age/Info:	NO	Party At Fault:	UNKNOWN
TP Injury Involved?		Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	OPEL INSIGNIA GRANDSPORT	Vehicle Reg. Date:	01/04/2019
Vehicle Colour:	B16DTH, 1.6 TURBO (A)		
Engine No:	SILVER		
Odometer:	A2183178JSUX0330	Chassis No:	W0VZM6EF3K1034528
	237784 KM		

*Not Ashwin  
Remy B & Paim  
EX B2000*

*83540 off*

Paint Type: NO  
Total Loss? 5 ✓  
Est. Duration of Repair (day)

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

**COST OF CLAIMS**

Parts	Amount
Miscellaneous Items	6,205.10
Labour	49.00
Paintwork Labour	2,280.00
Towing	0.00
	0.00
<b>Calculated Gross Total (S\$)</b>	<b>8,534.10</b>
- Excess (S\$)	2,000.00
(S\$)	6,534.10
+ GST 7.00% (S\$)	457.39
<b>Nett Amount (S\$)</b>	<b>6,991.49</b>

This claim is handled by: LIM JIA HAW

**REPAIR DETAILS**

**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)  
 Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39196928	*Front Door RH	0.00	0.00	*2,129.00F
2	1	13531200	*FRONT DOOR HANDLE	0.00	0.00	*307.00F
3	1	13533640	*FRONT DOOR INNER LOCK RH	0.00	0.00	*422.00F
4	1	13583613	*FRONT DOOR HINGE UPPER RH	0.00	0.00	*44.00F
5	1	13583618	*FRONT DOOR HINGE LOWER RH	0.00	0.00	*44.00F
6	1	39185963	*FRONT DOOR CHECK RH	0.00	0.00	*97.00F
7	1	39176501	*FRONT DOOR INNER TRIMBOARD RH	0.00	0.00	*784.00F
8	1	39125440	*FRONT FENDER RH	0.00	0.00	*450.00F
9	1		*FRONT FENDER INNER SHIELD OUTER	0.00	0.00	*95.00F
10	1	YQ00011480	*Front Fender Signal Lamp/Cover RH	0.00	0.00	*26.00F
11	1	39148126	*FRONT side mirror assy RH	0.00	0.00	*514.00F
12	1	39081047	*Cover , mirror RH	0.00	0.00	*85.00F
13	1	13343699	*Motor , mirror adjustment RH	0.00	0.00	*186.00F
14	1	13312747	*Tyre rim - Alloy Rim	0.00	0.00	*458.00F

F=Franchise part.

Sub Total (S\$) 5,641.00  
 + Margin on L,N Items 10.00% (S\$) 564.10

Total Parts (S\$) 6,205.10

Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: