

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	09/10/2022
Vehicle Reg. No.:	SMK2413S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 TURBO (A)	Vehicle Reg. Date:	01/04/2019
Vehicle Colour:	SILVER	Chassis No:	W0VZM6EF3K1034528
Engine No:	A2183178JSUX0330		
Odometer:	237784 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	5 ✓

*NOT Authorised
Personnel B & Paint
Ex @ 2000*

Present Location: **MUNICH AUTOCARE PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	6,205.10
Miscellaneous Items	49.00
Labour	2,280.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$)	8,534.10
- Excess (S\$)	2,000.00
(S\$)	6,534.10
+ GST 7.00% (S\$)	457.39
Nett Amount (S\$)	6,991.49

This claim is handled by: **LIM JIA HAW**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)

Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39196928	*Front Door RH	RH 0.00	0.00	*2,129.00 F ✓
2	1	13531200	*FRONT DOOR HANDLE	Sm 0.00	0.00	*307.00 F ✓
3	1	13533640	*FRONT DOOR INNER LOCK RH	R 0.00	0.00	*422.00 F X
4	1	13583613	*FRONT DOOR HINGE UPPER RH	RH 0.00	0.00	*44.00 F ✓
5	1	13583618	*FRONT DOOR HINGE LOWER RH	R 0.00	0.00	*44.00 F X
6	1	39185963	*FRONT DOOR CHECK RH		0.00	*97.00 F 7
7	1	39176501	*FRONT DOOR INNER TRIMBOARD RH		0.00	*784.00 F 7
8	1	39125440	*FRONT FENDER RH	RH 0.00	0.00	*450.00 F ✓
9	1		*FRONT FENDER INNER SHIELD OUTER	Sm 0.00	0.00	*95.00 F X
10	1	YQ00011480	*Front Fender Signal Lamp/Cover RH	RH 0.00	0.00	*26.00 F ✓
11	1	39148126	*FRONT side mirror assy RH	Sm 0.00	0.00	*514.00 F X
12	1	39081047	*Cover , mirror RH	Sm 0.00	0.00	*85.00 F X
13	1	13343699	*Motor , mirror adjustment RH	Sm 0.00	0.00	*186.00 F X
14	1	13312747	*Tyre rim - Alloy Rim	Sm 0.00	0.00	*458.00 F X

F=Franchise part.

Sub Total (S\$)	5,641.00
+ Margin on L,N Items 10.00% (S\$)	564.10
Total Parts (S\$)	6,205.10

Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	7	FRONT FENDER INNERSHIELD CLIP SET	<i>nn</i> 49.00 X
Sub Total (S\$)			49.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION, WINDOW, SIDE MIRROR	New	<i>200</i> 80.00
2	TO REMOVE & REPLACE SIDE MIRROR & RIM	New	<i>nn</i> 120.00 X
3	WHEEL ALIGNMENT	New	<i>nn</i> 80.00 X
4	TO RESPRAY FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH, SIDE MIRROR RHAND ALL THE EFFECTED AREAS.	New	<i>5000</i> 1,000.00
5	TO DISMANTLE ,KNOCKING, PANEL BEATING, REFIX FRONT ACCIDENT POTION, FRONT FENDER RH, FRONT DOOR RH, ROKER PANEL RH, AND ALL THE EFFECTED AREAS.	New	<i>6000</i> 1,000.00
Gross Labour Cost (S\$)			2,280.00

Munich Autocare Pte Ltd/SMK2413S/11/10/2022 17:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >