



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4558R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	PANEL ASSY-REAR DOOR RH	TO REPAIR SEE LABOUR	2,147.90	-
1	W/STRIP ASSY-FR DR BELT	NOT NECESSARY	125.30	-
	LESS 20% DISCOUNT		-454.64	-
			1,818.56	-
	<b><u>NETT ITEMS</u></b>			
1	ZIG BOOK NOW APP LOGO REA (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-8.00	-8.00
			72.00	72.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF PANEL ASSY-REAR DOOR RH.		800.00	350.00
	SPRAYPAINT CHARGE.		600.00	500.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	120.00	-
			1,520.00	850.00
	<b>GRAND TOTAL</b>		<b>3,410.56</b>	<b>922.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>922.00</b>

Report Ref No. NS/INC22010050/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.