

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4781L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER-RR BUMPER#	TO REPAIR SEE LABOUR	481.10	-
1	PANEL-FENDER LH#	TO REPAIR SEE LABOUR	588.80	-
1	PANEL ASSY-FRONT DOOR LH#	TO REPAIR SEE LABOUR	1,797.20	-
	LESS 20% DISCOUNT		-573.42	-
			2,293.68	-
	NETT ITEMS			
1	ZIG BOOK NOW APP LOGO REA (N)	NECESSARY	80.00	80.00
1	FRT DOOR LOGO SONATA CTPL (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
	SPECIAL NETT ITEMS			
1	ADVERTISMENT STICKER-FENDER (SN)	NECESSARY	100.00	100.00
1	ADVERTISMENT STICKER-DOOR FRT (SN)	NECESSARY	100.00	100.00
1	ADVERTISMENT STICKER-DOOR RR (SN)	NECESSARY	100.00	100.00
			300.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF COVER- RR BUMPER#, PANEL-FENDER LH# & PANEL ASSY- FRONT DOOR LH#.		900.00	350.00
	SPRAYPAINT CHARGE.		1,200.00	1,000.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	120.00	-
			2,220.00	1,350.00
	GRAND TOTAL		4,953.18	1,789.50





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		1,789.50
(CONFIRMED)		

Report Ref No. NS/INC22010051/Gncm4

XING GUO QIANG

Automotive Assessor

M.MATAI, AMSAE-A

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser