

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: ERGO Insurance Pte Ltd

Accident Date : 03.10.2022

NOT Withheld
L1 Pump &
Pressure After Pairs
Ex & Fuel
6 days

Policy No: DMPG22009186

Date: 07.10.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Luxus" Reg. No. SJV822K			
1pc	Bonnet		B 950.00 ✓
2pcs	Bonnet Hinges	38.00	NIS DIT 76.00 ✓
2pcs	Bonnet Locks	65.00	DIT 130.00 ✓
2pcs	Bonnet Dampers	110.00	IN 220.00 X
1pc	Bonnet Rubber Seal		IN 30.00 ✓
1pc	Grille		CM 390.00 ✓
1pc	Grille Top Chrome Moulding		DIT 200.00 ✓
1pc	Grille Lower Chrome Moulding		IN 330.00 ✓
1pc	Grille Top Rubber Seal		IN 28.00 ✓
1pc	Headlamp LH (LED)		BU 2,500.00 ✓
1pc	Headlamp LED Control Module		350.00 ?
1pc	Headlamp Washer LH		CM 230.00 ✓
1pc	Headlamp Washer Cover LH		IN 16.00 ✓
1pc	Headlamp Washer Cover Base LH		CM 16.00 ✓
1pc	Headlamp Washer Tube LH		IN 25.00 ✓
1pc	Brace Panel		R 95.00 X
1pc	Front Bumper		IN 300.00 ✓
12pcs	Front Bumper Clips	1.50	IN 18.00 ✓
1pc	Front Bumper Bracket LH		R 105.00 ✓
1pc	Front Bumper Sponge		IN 55.00 ✓
1pc	Front Bumper Reinforcement		R 260.00 ✓
1pc	Front Bumper Top Retainer LH		CM 55.00 ✓
1pc	Front Bumper Center Air Grille		my CM 370.00 ✓
1pc	Front Bumper Lower Air Grille RH		CM 35.00 ✓
2pcs	Front Bumper Sensors	135.00	270.00 ?
4pcs	Front Bumper Sensor Holders	15.00	60.00 ?
1pc	Front Bumper Sensor Wiring Harness		IN 360.00 ✓
1pc	Front Bumper Number Plate Base Holder		my CM 95.00 ✓
1pc	Front Bumper Lower Lip		my CM 150.00 ✓
1pc	Front Bumper Lower Side Lip LH		IN 70.00 ✓
1pc	Front Bumper Lower Splash Guard		320.00 ?
1pc	Front Bumper Tow Point Cover LH		IN 25.00 ✓
1pc	Front Bumper Fog Lamp LH		my CM 180.00 ✓
1pc	Front Bumper Fog Lamp Cover		IN 35.00 X
1pc	Front Bumper Fog Lamp Cover Moulding		IN 45.00 X
1pc	Front Bumper Cornering Lamp		220.00 ?
1pc	Front Bumper Corner Retainer LH		CM 35.00 ✓
		B/F	8,649.00

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: ERGO Insurance Pte Ltd

Policy No: DMPG22009186

Date: 07.10.2022

Accident Date : 03.10.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Lexus" Reg. No. SJV822K			
		C/F	8,649.00
1pc	Support Panel		750.00 ✓
1pc	Support Panel Top Garnish		180.00 ✓
1pc	Radiator		750.00 ?
1pc	Radiator Fan Assy		420.00 X
1pc	Radiator Fan ECU LH		195.00 ?
1pc	Air Con Condenser		680.00 ?
1pc	Air Con Condenser Side Air Guide (Top) LH		40.00 —
1pc	Air Con Condenser Side Air Guide (Bottom) LH		35.00 —
1pc	Battery		200.00 ?
1pc	Battery Tray		35.00 ?
1pc	Air Cleaner Box		450.00 ✓
1pc	Air Cleaner Box Cold Air Intake Duct		58.00 —
1pc	ATM Intercooler		290.00 X
1pc	ATM Intercooler Cowling		155.00 X
1pc	Transmission Cooler		200.00 X
1pc	Transmission Oil Thermostat		320.00 X
1pc	Converter Assy Eco Run		370.00 ?
1pc	Front Fender LH		360.00 —
1pc	Front Fender Arch Protector		250.00 —
1pc	Front Fender Inner Top Garnish		145.00 X
1pc	Main Fuse Box Assy LH		850.00 X
	Cost Plus 10%		15,382.00
			1,538.20
			16,920.20
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Refill Air Con Gas		100.00 ✓
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		50.00 ✓
	Labour Charge - Panel Beating, Repairing of Front Chassis Member, Inner Panel, Front O/S Fender etc. Cnt, Weld Support & Part Replacement		900.00 0501
	To Respray Affected Areas		800
			1,000.00
		Total	19,000.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: