



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22010057/Rny3m4 Date: 01/12/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6166A	Veh. Inspected	GBH 9492M	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/09/22/2079	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	12/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35Y60K211579	Colour	GREY	
Odometer	211701 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/R15C	MAXMILER	7 mm	
L/H Front Tyre	195/R15C	MAXMILER	7 mm	
R/H Rear Tyre	155 R15C (D/D)	MAXMILER	5/5 mm	
L/H Rear Tyre	155 R15C (D/D)	MAXMILER	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2022	Inspection Date	13/10/2022	
Survey held at	LIAN HONG SENG MOTOR WORKS BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	