

**WTS Engineering Pte Ltd**

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

## Quotation

DATE: 29/09/22

VEHICLE NO: WC292K

DRIVER: TEO CHOONG YONG

ATTENTION TO:

PREPARED BY: Colin

LOCATION: Gul Workshop

Q REF No: Q22/09/1293

DEPARTMENT: WTS Mixer Truck Department

ACCIDENT DATE: 29/09/22

REF No: JW/0922/253

S/N	Description	Qty	Cost per Unit	Amount S\$
<b>Spare Parts</b>				
1	RHS BUMPER TOP PLASTIC COVER	1	96	96.00
2	RHS FOOTPLATE ASSY	1	357	357.00
3	RHS CORNER PROTECTOR	1	108	108.00
4	PLASTIC FRONT MUDGUARD	1	156.8	156.80
5	RHS BUMPER BRACKET	1	160	160.00
6	FRONT MUDGUARD BRACKET	1	120	120.00
7	RHS FOOTPLATE ASSY BRACKET	1	150	150.00
<b>Labour Costs</b>				
1	DISMANTLE & PLACE DAMAGED 1. PLASTIC FRONT MUDGUARD 2. FRONT MUDGUARD BRACKET 3. RHS BUMPER TOP PLASTIC COVER 4. RHS CORNER PROTECTOR 5. RHS FOOTPLATE ASSY 6. RHS FOOTPLATE ASSY BRACKET 7. RHS BUMPER BRACKET	1	750	750.00
2	PANEL BEATING ON BUMPER DAMAGED AREA	1	350	350.00
<b>Spray Paint</b>				
1	Spray Painting  PUTTY AND SPRAY PAINTING ON THE DAMAGED PARTS	1	600	600.00
<b>TOTAL:</b>				<b>2,847.80</b>
<b>Total Amount</b>				<b>SGD 2,847.80</b>

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department