

Let Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 10/10/2022

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

M/S AIG

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR HONDA STREAM - SJL4652K

DOA : 10/10/2022

Not Authorized
12/10/22
L / S #1300/
2 days.
Wang H. Heng

S/N	QTY	DESCRIPTION			
1	1 PC	TAILGATE	2 X	\$	991.10 X
2	1 PC	TAILGATE LOCK	11 X	\$	124.50 X
3	1 PC	TAILGATE LOWER LOCK	11 X	\$	207.70 X
4	1 PC	TAILGATE RUBBER	11 X	\$	145.50 X
5	1 PC	TAILGATE HONDA LOGO	stream	\$	36.00 ✓
6	1 PC	TAILGATE INNER TRIM BOARD	11 X	\$	170.30 X
7	1 PC	REAR BUMPER	20/22	\$	665.40 704.90 ✓
8	1 PC	REAR BUMPER TOWING COVER	11 X	\$	14.80 X
9	1 PC	REAR W/S MOULDING	11 X	\$	27.70 X
10	1 PC	EXHUAUST MUFFLER CHROME PIPE	11 X	\$	121.80 X
11	1 PC	REAR END PANEL	2 X	\$	346.20 X
12	1 PC	REAR END PANEL GARNISH	11 X	\$	141.20 X
				\$	3031.70
			Disc -20%	\$	-606.34
				\$	2425.36
13	10PCS	REAR BUMPER CLIPS	11	\$	40.00 ✓
14	1 PC	NUMBER PLATE	11	\$	35.00 X
15	1 SET	REVERSE SENSOR	11	\$	280.00 200
16		REMOVE AND REFIX SEATS GARNISH , ETC	11	\$	120.00 X
17		REMOVE AND REFIX REAR WINDSCREEN	11	\$	120.00 X
18		REMOVE AND REFIX REAR SENSOR		\$	80.00 50
19		TUFF COAT	11	\$	120.00 X
20		WIRING CHECK		\$	120.00 20
21		LABOUR CHARGE		\$	1200.00 320
22		SPRAY PAINTING (REAR)		\$	1000.00 450
			Total	\$	5540.36

2 set. Sealant - #80.00 11 X

2-701.4
202
561.12
240
840
1601.12