



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG			Ref: CC4/ASM22010071/Rpa3q2 Date: 21/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3426A	Veh. Inspected	SHB 5329P
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04CQ6	Excess (\$)	0.00
	Assign From		Assign Date	12/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU603573255	Colour	MAROON
	Odometer	417504 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	GITI	6 mm
	L/H Front Tyre	195/65 R15	GITI	6 mm
	R/H Rear Tyre	195/65 R15	GITI	6 mm
	L/H Rear Tyre	195/65 R15	GITI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/10/2022	Inspection Date	12/10/2022
	Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	