



Section A - Accident Details

Registration Number	SHB5329P
Case Reference Number	TAX/10/22/2019
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHRISTOPHER FOO SZE WOON (CHRISTOPHER FU SIWEN)
Type of Accident	Head to Rear
Accident Date and Time	5/10/2022 9:21 PM
Accident Reported Date and Time	6/10/2022 3:33 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116540
Special Instruction to ARC, if any	TP/REAR PORTION/AXA
Prepared Date and Time	12/10/2022 10:56 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$918.00	\$300.00
Total Spare Part Cost	\$2,668.25	\$1,220.69
Total Other Cost	\$796.88	(\$120.69)
TOTAL COST	\$5,059.13	\$1,600.00 (L/S)
Lump Sum Total	\$5,050.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / AXA
ARC / Surveyor Sign Off Date	18/10/2022 10:17 AM	17/10/2022 10:46 AM
Signature		
Remarks	Initial 5 days / sup 2 days / total 7 days	lump sum repair / resurvey after repair

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2211-0308	Invoice Number	
Quotation Date	21.11.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00 ✓
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$100.00 ✓
Total Spray Painting & Panel Beating	\$918.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$417.57)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88 ✓
Total Other Costs	\$796.88	(\$120.69)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	30.00	\$5.25	Replace	Replace
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Not Given
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given

R
X
X
X
X
X
✓
X
X
X
X

ALL X NN
NEC
ALL X NN

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 11/01/2023

User ID : PohSuan

		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	30.00	\$436.45	Replace	Replace	√ DE
		5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X ALL X NN
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
		5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
Total					\$3,475.50		\$441.70			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	30.00	\$335.23	Replace	Replace
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	30.00	\$252.07	Replace	Replace
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	30.00	\$11.69	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
Total					1,035.70		778.99		

1,220.69
 + 200.00
 + 596.88

 2,017.57
 -20%

 1,614.06

L/S \$1,600/-

