



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0873/2022/EQ
DATE : 11-Oct-22
WIP : 45407

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

11 days exclude 1 PH & 2 Sundays

Johnny Boo 30 Nov 22

OWNER'S NAME : MR YEE CHI YWEE
ADDRESS : 10B HOUGANG STREET 11
#10-39, THE MINTON
SINGAPORE 534078
TELEPHONE : HP +65 81836449
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100504302-05
VEHICLE NO : **SLM 5505 S**
MODEL CODE : AUDI S3 SB 2.0 TFSI QU
MODEL YEAR : 29/3/2017
ENGINE NO : DJH 008972
CHASSIS NO : WAUZZZ8V3HA103207
MILEAGE : 64,489
DATE IN : 10-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-22
PLACE OF ACCIDENT : TPE, JUST BEFORE KPE EXIT 7A

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 5505 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER BOTH FRONT HEADLIGHTS CONTROL UNIT AND POWER MODULES.	S/N \$	700.00	\$ 250.00
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM.	S/N \$	1,200.00	\$ 1,200.00
4	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	\$ 480.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	\$ 400.00
TOTAL LABOUR CHARGES		:	\$ 3,140.00	\$ 2,690.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 5505 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE TEST.	<i>C/F</i> S/N	\$ 200.00	\$ 2,690.00 \$ 150.00
7	TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY. RENEW WINDOW SLOT SEAL.	S/N	\$ 700.00	<i>na</i>
8	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>(S3 2 Ltr Lock carrier x 3 days)</i>		\$ 5,600.00	\$ 2,750.00
9	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, AND BOTH FRONT DOORS.		\$ 5,200.00	\$ 2,200.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 15,032.00	\$ 7,982.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 5505 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,664.00	\$	2,131.20
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	\$	34.24
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 332.00		
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 636.00		
7	FRONT BUMPER TRIM - LH / RH	2	\$ 388.00		
8	RADIATOR GRILLE	1	\$ 1,578.00	\$	1,262.40
9	"S3" INSCRIPTION	1	\$ 133.00	\$	106.40
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00		
11	FRONT BUMPER REINFORCEMENT BEAM COVER	2	\$ 272.00	\$	108.80
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	\$	168.80
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	\$	677.20
14	AIR CONDITIONER STICKER	1	\$ 9.00	\$	6.64
15	CAUTION SIGN STICKER	1	\$ 16.00	\$	12.40
16	FRONT FENDER - LH / RH	2	\$ 1,908.00		
17	FRONT FENDER RIVET	16	\$ 61.00		
18	FRONT FENDER BRACKET - LH / RH	2	\$ 112.00		
19	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 136.00		
20	BONNET	1	\$ 3,370.00	\$	2,696.00
SUB TOTAL SPARE PARTS			\$ 13,343.00	\$	7,204.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 5505 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	<i>REMARKS</i>	
		<i>C/F</i>		<i>\$</i>	<i>7,204.08</i>
21	BONNET ATTACHMENT PARTS	1	\$ 172.00		
22	BONNET HINGE - LH / RH	2	\$ 136.00	<i>\$</i>	<i>108.48</i>
23	COWL SIDE PANEL SEAL - LH / RH	2	\$ 92.00		
24	BONNET EDGE PROTECTION	1	\$ 31.00	<i>\$</i>	<i>24.72</i>
25	BONNET CATCH HOOK	1	\$ 100.00		
26	BONNET STRIKER - LH / RH	2	\$ 246.00	<i>\$</i>	<i>98.00</i>
27	BONNET CATCH HOOK	1	\$ 71.00	<i>\$</i>	<i>56.32</i>
28	BONNET LOCK - LH / RH	2	\$ 455.00	<i>\$</i>	<i>182.00</i>
29	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
30	HEADLIGHT - LH / RH	2	\$ 11,758.00	<i>\$</i>	<i>4,703.20</i>
31	LOCK CARRIER	1	\$ 806.00	<i>\$</i>	<i>644.80</i>
32	RADIATOR AIR GUIDE - LH / RH	2	\$ 56.00	<i>\$</i>	<i>44.32</i>
33	A/C CONDENSER	1	\$ 605.00		
34	FRONT PARKING AID SEAL RING	2	\$ 25.00		
35	CHARGE AIR COOLER	1	\$ 1,338.00		
36	RADIATOR	1	\$ 1,093.00	<i>\$</i>	<i>874.40</i>
37	RADIATOR RUBBER BUSH	2	\$ 90.00		
38	FRONT WINDSCREEN	1	\$ 1,206.00	<i>\$</i>	<i>964.80</i>
39	FRONT RAIN SENSOR GEL FOIL	1	\$ 131.00	<i>\$</i>	<i>104.40</i>
40	FRONT WING MIRROR RETAINER	1	\$ 23.00	<i>\$</i>	<i>18.32</i>
SUB TOTAL SPARE PARTS			\$ 18,498.00	\$	15,027.84

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 5505 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
		C/F		\$	15,027.84
41	MIRROR PRIMER	1	\$	22.00	\$ 17.36
42	PLENUM CHAMBER COVER	1	\$	199.00	\$ 159.20
43	FRONT WATER DEFLECTOR STRIP - LH / RH	2	\$	150.00	
44	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	2	\$	604.00	
45	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00
46	Add parts		\$	308.00	\$ 244.08
47	SUNDRIES		\$	600.00	\$ 32.24
TOTAL SPARE PARTS		:	\$	33,784.00	\$ 15,540.72
TOTAL LABOUR CHARGES		:	\$	15,032.00	\$ 7,982.00
GRAND TOTAL		:	\$	48,816.00	\$ 23,522.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/11/22



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0873/2022/EQ 18-Oct-22 CHANG 1 of 1 SLM 5505 S AUDI S3 SB 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
Parts			
1	INTAKE AIR GUIDE - LOWER	\$ 59.00	\$ 46.56
2	INTAKE AIR GUIDE - UPPER COVER	\$ 30.00	\$ 23.84
3	INTAKE AIR GUIDE - CENTER	\$ 36.00	\$ 28.08
4	FRONT REINFORCEMENT BEAM COVER	\$ 136.00	\$ 108.80
5	OUTER TEM. SENSOR BRACKET	\$ 21.00	\$ 16.32
6	QUICK ACTING COUPLING	\$ 26.00	\$ 20.48
GRAND TOTAL		\$ 308.00	\$ 244.08

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT