

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0874/2022/EQ
DATE : 11-Oct-22
WIP : 45409

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

26 days exclude 5 Sundays & 1 PH

Johnny Boo 27 Dec 22

OWNER'S NAME : MS MILLIE LENG MI LIN
ADDRESS : 107 BUKIT WAY
SINGAPORE 587785

TELEPHONE : HP +65 90613201
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210153572
VEHICLE NO : **SJA 5555 J**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 27/12/2021
ENGINE NO : DEM 034415
CHASSIS NO : WAUZZZF56NA002175
MILEAGE : 11,325
DATE IN : 10-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-22
PLACE OF ACCIDENT : NORTH BUONA VISTA ROAD AND DOVER
ROAD / AYER RAJAH AVE JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 5555 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$	800.00	\$	800.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$	360.00
3	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	300.00	\$	300.00
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	\$	400.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	\$	1,600.00
TOTAL LABOUR CHARGES		:	\$ 3,460.00	\$	3,460.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 5555 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		C/F		\$ 3,460.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	\$ 1,600.00
7	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY, INCLUDING REAR AXLE AND PROPELLOR SHAFT. RENEW ACCORDINGLY.	S/N \$	2,800.00	\$ 480.00
8	TO REMOVE AND REINSTALL FUEL TANK ASSY.	S/N \$	600.00	na
9	TO SETUP VEHICLE ON CAR-O-LINER FOR REPAIR.	S/N \$	2,400.00	\$ 2,400.00
10	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. TO REPAIR REAR LID. CUT OUT AND WELD LHS REAR FENDER, LHS BOTTOM PLATE, LHS INNER WHEEL HOUSING, LHS OUTER WHEEL HOUSING, LHS REAR INNER SIDE PANEL AND LHS D-PILLAR REINFORCEMENT. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	15,200.00	\$ 5,000.00
TOTAL LABOUR CHARGES		:	\$ 22,600.00	\$ 12,940.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 5555 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		C/F		\$ 12,940.00
11	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, LHS INNER/OUTER WHEEL HOUSING, LHS BOTTOM PLATE, LHS D-PILLAR REINFORCEMENT, LHS INNER SIDE PANEL, LHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES, END PANELLING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	\$	8,000.00	\$ 4,125.00
12	TO RENEW LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 520.00
13	Add labour	\$	1,200.00	\$ 800.00
13a	To repair rear left rim (Given item 67 but owner sent for repair)	\$	140.00	\$ 140.00
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 36,304.00	\$ 18,909.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 5555 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,609.00	\$	2,087.20
2	REAR BUMPER SECURING STRIP - LOWER	1	\$ 125.00	\$	100.00
3	REAR BUMPER SECURING STRIP - UPPER	1	\$ 249.00	\$	198.80
4	REAR BUMPER SPOILER	1	\$ 276.00	\$	220.80
5	REAR BUMPER BRACKET - LH / RH	2	\$ 456.00	\$	182.00
6	REAR BUMPER REFLECTOR - LH / RH	2	\$ 96.00	\$	76.48
7	REAR OUTER TAIL LIGHT - LH	1	\$ 1,269.00	\$	1,015.20
8	REAR OUTER TAIL LIGHT TRIM - LH	1	\$ 34.00	\$	26.48
9	REAR INNER TAIL LIGHT - LH	1	\$ 1,135.00	\$	908.00
10	REAR INNER TAIL LIGHT TRIM - LH	1	\$ 34.00	\$	26.48
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	\$	904.80
12	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 32.00	\$	25.28
13	REAR BUMPER GUIDE SECTION - LH	1	\$ 49.00	\$	39.04
14	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 52.00	\$	20.16
15	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 188.00	\$	149.60
16	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 484.00		
17	REAR RETAINER CONTROL UNIT	1	\$ 9.00		
18	REAR BOOT LID OPENING SENSOR LINE	1	\$ 228.00		
19	AERIAL KEY ACCESS	1	\$ 120.00		
20	AERIAL RETAINER - LH	1	\$ 29.00	\$	22.48
SUB TOTAL SPARE PARTS			\$ 8,605.00	\$	6,002.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 5555 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 6,002.80
21	TELEPHONE AERIAL	1 \$	192.00	\$ 153.60
22	REAR VENT TRIM	1 \$	75.00	\$ 59.52
23	REAR PARKING AID SENSOR - INNER / OUTER	2 \$	797.00	
24	REAR PARKING AID SENSOR - SIDE	1 \$	266.00	\$ 212.00
25	REAR PARKING AID SEAL RING	4 \$	10.00	
26	REAR BUMPER WIRING SET	1 \$	449.00	\$ 358.80
27	PACKING ADHESIVE	1 \$	21.00	\$ 16.80
28	AUDI EMBLEM	1 \$	163.00	\$ 130.00
29	"A5" INSCRIPTION	1 \$	104.00	\$ 82.80
30	REAR SIDE PANEL - LH	1 \$	4,076.00	\$ 3,260.80
31	REAR QUARTER GLASS - LH	1 \$	798.00	\$ 638.00
32	WINDOW PRIMER	1 \$	22.00	\$ 17.36
33	REAR BOTTOM PLATE - LH OUTER	1 \$	506.00	\$ 404.40
34	REAR WHEEL HOUSING - LH OUTER	1 \$	715.00	\$ 571.60
35	D-PILLAR REINFORCEMENT - LH	1 \$	305.00	
36	SIDE PANEL REINFORCEMENT - LH	1 \$	229.00	
37	REAR WHEEL HOUSING CONNECTING PLATE - LH	1 \$	62.00	
38	REAR WHEEL HOUSING ATTACHMENT PARTS - LH	1 \$	1,561.00	
39	REAR CROSS PANEL	1 \$	379.00	
40	REAR CROSS PANEL REINFORCEMENT	1 \$	668.00	
SUB TOTAL SPARE PARTS			\$ 11,398.00	\$ 11,908.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 5555 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 11,908.48
41	REAR WHEEL HOUSING LINER - LH	1	\$ 299.00	\$ 238.20
42	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 176.00	
43	REAR CROSS PANEL TRIM	1	\$ 399.00	
44	REAR LUGGAGE COMPARTMENT FLOOR COVERING	1	\$ 786.00	
45	REAR LUGGAGE COMPARTMENT TRIM - LH	1	\$ 1,153.00	
46	EXHAUST SILENCER - LH	1	\$ 1,226.00	\$ 980.80
47	EXHAUST SILENCER BRACKET	1	\$ 45.00	\$ 48.00
48	EXHAUST CENTRE SILENCER	1	\$ 956.00	
49	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 766.00	\$ 306.00
50	EXHAUST HEAT SHIELD - LH	1	\$ 169.00	\$ 134.80
51	EXHAUST HEAT SHIELD - CENTER	1	\$ 76.00	
52	REAR SUPPORT FRAME	1	\$ 3,643.00	
53	REAR LOWER ARM CONTROL	1	\$ 963.00	
54	REAR UPPER ARM CONTROL - LH	1	\$ 624.00	
55	REAR SUSPENSION - LH FRONT	1	\$ 137.00	
56	REAR SUSPENSION - LH REAR	1	\$ 501.00	
57	REAR TRACK ROD - LH	1	\$ 188.00	
58	REAR WHEEL BEARING HOUSING - LH	1	\$ 1,097.00	
59	REAR WHEELHUB BEARING	1	\$ 723.00	
60	REAR STONE CHIP GUARD - LH	1	\$ 49.00	
SUB TOTAL SPARE PARTS			\$ 13,976.00	\$ 13,616.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 5555 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>13,616.28</i>
61	REAR GAS SHOCK ABSORBER	1	\$ 342.00		
62	REAR COUPLING ROD	1	\$ 94.00		
63	REAR ANTI-ROLL BAR	1	\$ 456.00		
64	REAR LEVEL SENSOR - LH	1	\$ 363.00		
65	REAR ATTACHMENT PARTS	1	\$ 136.00		<i>108.8</i>
66	ADHESIVE TAPES	1	\$ 221.00		<i>176.8</i>
67	REAR LEFT RIM	1	TBC		
68	ACRYLIC SEALANT	S/N	\$ 180.00	<i>\$</i>	<i>180.00</i>
69	CAVITY WAX	S/N	\$ 140.00	<i>\$</i>	<i>140.00</i>
70	STONE CHIP	S/N	\$ 180.00	<i>\$</i>	<i>180.00</i>
71	METAL FILLER POWDER	S/N	\$ 280.00	<i>\$</i>	<i>280.00</i>
72	SUPPLEMENTARY		<i>\$ 585.00</i>	<i>\$</i>	<i>487.28</i>
73	SUPPLEMENTARY		<i>\$ 504.00</i>	<i>\$</i>	<i>292.64</i>
72	SUNDRIES		\$ 1,000.00	<i>\$</i>	<i>201.96</i>
TOTAL SPARE PARTS		:	\$ 38,460.00	<i>\$</i>	<i>15,663.76</i>
TOTAL LABOUR CHARGES		:	\$ 36,304.00	<i>\$</i>	<i>18,909.00</i>
GRAND TOTAL		:	\$ 74,764.00	<i>\$</i>	<i>34,572.76</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0874/2022/EQ 19-Oct-22 CHANG 1 of 1 SJA 5555 J AUDI A5 SPORTBACK 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR LIGHT REFLECTOR - RH INNER	\$ 48.00	\$ 38.24
2	SOUND ABSORBER FOR SIDE WALL	\$ 119.00	\$ 95.20
3	ADAPTER AERIAL WIRE	\$ 183.00	\$ 52.80
4	AERIAL CONNECTION LINE	\$ 154.00	\$ 106.40
	GRAND TOTAL	\$ 504.00	\$ 292.64

For Premium Automobiles Pte Ltd

Authorised Signature

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0874/2022/EQ 27-Oct-22 GLORY 1 of 1 SJA 5555 J AUDI A5 SPORTBACK 2.0 TFSI	
Quantity	Description		Unit Price	Amount
LABOURS				
1	TO REPAIR SPARE WHEEL HOUSING.	1	\$ 400.00	\$ 250.00
2	TO RESPRAY SPARE WHEEL HOUSING.	1	\$ 800.00	\$ 550.00
GRAND TOTAL			\$ 1,200.00	\$ 800.00

For Premium Automobiles Pte Ltd

Authorised Signature



Supplementary Estimate-3

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0874/2022/EQ 3-Nov-22 GLORY 1 of 1 SJA 5555 J AUDI A5 SPORTBACK 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>PARTS</u>				
1	RETAINER FOR CONTROL UNIT	1	\$ 89.00	\$ 71.20
2	SUPPORT FOR CENTRAL CONTROL UNIT	1	\$ 39.00	\$ 30.48
3	SIDE MEMBER TRIM ATTACHMENT PARTS	1	\$ 136.00	\$ 108.80
4	SIDE MEMBER TRIM ADHESIVE TAPE	1	\$ 221.00	\$ 176.80
5*	1/4 glass sealant	1	\$ 100.00	\$ 100.00
GRAND TOTAL			\$ 585.00	\$ 487.28

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT