

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0875/2022/EQ
DATE : 11-Oct-22
WIP : 45555

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHONG LEE FONG
ADDRESS : 8 BEE SAN AVENUE
SINGAPORE 589963

TELEPHONE : HP +65 97876383
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 18000800001
VEHICLE NO : **SJT 9963 M**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 20/7/2018
ENGINE NO : CVK 064081
CHASSIS NO : WAUZZZF49JN015027
MILEAGE : 61,333
DATE IN : 10-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-22
PLACE OF ACCIDENT : LOWER DELTA FLYOVER

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJT 9963 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER BOTH FRONT HEADLIGHTS CONTROL UNIT AND POWER MODULES. <i>250 Y2</i>	S/N \$ 700.00	<i>500</i>
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	S/N \$ 1,200.00	/
4	TO DISMANTLE FRONT BUMPER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>2 x 550</i>	\$ 4,200.00	<i>1000</i>
5	TO RESPRAY FRONT BUMPER AND BONNET. <i>550 X2</i>	\$ 1,800.00	<i>1100</i>
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 8,572.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 9963 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / OK	1	\$	2,377.00	
2	FRONT BUMPER FIXING PARTS X	1	\$	612.00	
3	FRONT BUMPER GRILLE - CENTER ?	1	\$	219.00	
4	RADIATOR GRILLE / OK	1	\$	1,478.00	
5	FRONT PARKING AID SENSOR - INNER / OUTER ?	2	\$	531.00	
6	FRONT PARKING AID SEAL RING / OK	4	\$	10.00	
7	FRONT BUMPER FOAM FILLER PIECE ?	1	\$	139.00	
8	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	899.00	
9	FRONT REINFORCEMENT BEAM SUPPORT - LH / RH ?	2	\$	64.00	
10	FRONT BUMPER BRACKET - CENTER / OK	1	\$	154.00	
11	FRONT REINFORCEMENT BEAM BRACKET - LH / RH ?	2	\$	508.00	
12	FRONT BUMPER TOP COVER / OK	1	\$	143.00	
13	CAUTION SIGN STICKER / OK	1	\$	16.00	
14	AIR CONDITIONER STICKER / OK	1	\$	9.00	
15	BONNET / OK	1	\$	3,425.00	
16	BONNET ATTACHMENT PARTS X	1	\$	431.00	
17	BONNET IMPACT PROTECTION - CENTER / LH / RH / OK	3	\$	93.00	
18	BONNET HINGE - LH / RH ?	2	\$	680.00	
19	BONNET STRIKER - LH / RH ?	2	\$	112.00	
20	BONNET LOCK - LH / RH /	2	\$	455.00	
SUB TOTAL SPARE PARTS		:	\$	12,355.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 9963 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET BOWDEN CABLE - CENTER ✓ BT	1	\$ 64.00	
22	BONNET RELEASE CABLE ?	1	\$ 64.00	
23	HEADLIGHT - LH / RH ✓ GR	2	\$ 16,588.00	
24	LOCK CARRIER ?	1	\$ 1,478.00	
25	RADIATOR AIR GUIDE - LH INNER ?	1	\$ 32.00	
26	RADIATOR AIR GUIDE - LH OUTER ?	1	\$ 14.00	
27	RADIATOR AIR GUIDE - RH INNER ?	1	\$ 32.00	
28	RADIATOR AIR GUIDE - RH OUTER ?	1	\$ 14.00	
29	RADIATOR AIR GUIDE - CENTER ?	1	\$ 19.00	
30	CHARGE AIR COOLER ?	1	\$ 654.00	
31	A/C CONDENSER ✓ ON	1	\$ 683.00	
32	A/C CONDENSOR O - RING ?	1	\$ 13.00	
33	A/C CONDENSOR SEAL RING ?	1	\$ 12.00	
34	A/C PRESSURE SENSOR ?	1	\$ 206.00	
35	A/C HIGH-PRESSURE SWITCH SAFETY SWITCH VALVE ?	1	\$ 53.00	
36	RADIATOR ?	1	\$ 1,013.00	
37	READY-MIX COOLANT ?	4	\$ 198.00	
38	RADIATOR FAN RING ?	1	\$ 292.00	
39	RADIATOR FAN CONTROL UNIT ?	1	\$ 2,489.00	
40	FRONT NO PLATE ✓ BT	S/N	\$ 60.00	
41	SUNDRIES ?		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 36,733.00	
TOTAL LABOUR CHARGES		:	\$ 8,572.00	
GRAND TOTAL		:	\$ 45,305.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (LKK)
: 12/12/22, 12:11 P
: 00- M AL
: EXCESS?
: PIP
: by RL y. 7 days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT