



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|----------------------------|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR22010081/Rqy3e2 | |
| | | | Date: 16/02/2023 | |
| | | | Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHB 1380R | Veh. Inspected | SMY 8825Z |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | TAX/10/22/2025 | Excess (\$) | 0.00 |
| | Assign From | HUA YEN | Assign Date | 12/10/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MERCEDES BENZ GLB200 PROGRESSIVE | c.c | 1332 |
| | Engine No. | HIDDEN | Year of Reg. | 2021 |
| | Chassis No. | W1N2476872W072437 | Colour | BLUE |
| | Odometer | 34812 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | FAIR | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 235/55 R18 | PIRELLI | 6 mm |
| | L/H Front Tyre | 235/55 R18 | PIRELLI | 6 mm |
| | R/H Rear Tyre | 235/55 R18 | PIRELLI | 6 mm |
| | L/H Rear Tyre | 235/55 R18 | PIRELLI | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 07/10/2022 | Inspection Date | 03/01/2023 |
| | Survey held at | CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ) | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |