



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMY8825Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 60200
Reg No/Reg Date SMY8825Z / 19/02/2021
Date In/Mileage 03/01/2023/ 34812
Chassis No W1N2476872W0724370
Engine No 28291480435592
Make/Model MB/GLB 200
Colour/Trim 026 667 Demin Blue / 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	21/01/2023/ 11:50		371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : PNPV2022-0000563 // 7-10-2022								
DRIVE IN/TP VEH NUMBER : 8-10-2022 // SHB1380R - FIRST CAPITAL								
DATE IN/DATE SURVEY: 3-1-2023 // RASUL - LKK								
DIRECT SETTLEMENT BY: 17-10-2022 // ANA - SAS								
A BPILAB	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							960.00
A BPIRES	RESpray REAR BUMPER						0.05	800.00
A BPILAB	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT						0.10	380.00
A BPILAB	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT							120.00
X REAR BUMPER					1.00	1353.32	00.00	1353.32
X REAR BUMPER LOWER BLACK TRIM					1.00	506.46	00.00	506.46
X REAR BUMPER LOWER CHROME TRIM					1.00	1300.54	00.00	1300.54
X REAR BUMPER STEP PLATE					1.00	179.41	00.00	179.41
X REFLECTING EMITTER					1.00	42.09	00.00	42.09

Confirmed & accepted by

Nett 5,641.82
8% GST on 5641.82 451.35
Total Payable 6,093.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMY8825Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No **60200**
Reg No/Reg Date **SMY8825Z / 19/02/2021**
Date In/Mileage **03/01/2023/ 34812**
Chassis No **W1N2476872W0724370**
Engine No **28291480435592**
Make/Model **MB/GLB 200**
Colour/Trim **026 667 Demin Blue / 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	21/01/2023/ 11:49	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : PNPV2022-0000563 // 7-10-2022 DRIVE IN/TP VEH NUMBER : 8-10-2022 // SHB1380R - FIRST CAPITAL DATE IN/DATE SURVEY: 3-1-2023 // RASUL - LKK DIRECT SETTLEMENT BY: 17-10-2022 // ANA - SAS X REFLECTING EMITTER	1.00	42.09	00.00	42.09

Confirmed & accepted by

8% GST on **Nett 42.09**
3.37
Total Payable 45.46

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG