



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE		Ref: CS/ASM22010092/Acy3m4 Date: 09/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7070R	Veh. Inspected	SLA 264H
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04CLF	Excess (\$)	0.00
Assign From	OH VALE	Assign Date	11/10/2022
2. Vehicle Particulars & Condition			
Make & Model	MINI COOPER	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMWZP32090T761297	Colour	SILVER
Odometer	75032 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/45 R17	MICHELIN	6 mm
L/H Front Tyre	205/45 R17	MICHELIN	6 mm
R/H Rear Tyre	205/45 R17	MICHELIN	6 mm
L/H Rear Tyre	205/45 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/10/2022	Inspection Date	11/10/2022
Survey held at	TSL AUTO GARAGE BLK 1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	