

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

TP AxA.
Celine.
WMW2P32090T761297

SLA264H Mini Copper S

No	Qty	Parts Description	Estimated Parts Price
1	1	Front sport bumper with spoiler complete assy <i>behd</i>	S 2,650.00 1480
2	2	Front bumper retainer <i>neu</i>	S 129.00 +
3	2	Front bumper bracket <i>neu</i>	S 118.00 +
4	1	Front bumper left inner upper garnish <i>neu</i>	S 125.00 +
5	1	Front bumper left inner lower garnish <i>neu</i>	S 125.00 +
6	1 set	Front support panel inner garnish <i>neu</i>	S 180.00 45
7	1	Front support assy <i>neu</i>	S 1,279.00 +
8	1	Front bumper reinforcement <i>neu</i>	S 455.00 +
9	1	Front bumper sponge <i>aukd</i>	S 175.00 ✓
10	1	Front bumper tow cover <i>neu</i>	S 88.00 +
11	1	Front bumper centre logo <i>neu</i>	S 128.00 ✓
12	1	Front left headlamp <i>aukd</i>	S 2,450.00 1850
13	1	Front left headlamp chrome protector <i>neu</i>	S 325.00 +
14	1	Front left headlamp module <i>neu</i>	S 875.00 +
15	1	Front left headlamp bracket <i>neu</i>	S 120.00 +
16	1	Front bonnet assy <i>neu</i>	S 2,850.00 +
17	1	Front bonnet chrome moulding <i>aukd</i>	S 196.00 ✓
18	1	Front left fog lamp <i>neu</i>	S 285.00 +
19	1	Front left fog lamp garnish <i>neu</i>	S 88.00 +
20	2	Front bonnet hinges <i>neu</i>	S 160.00 +
21	2	Front bonnet lock catch <i>neu</i>	S 86.00 +
22	1 set	Front bonnet lock mechanism <i>neu</i>	S 295.00 +
23	1	Front air con condenser assy <i>neu</i>	S 1,255.00 ✓
24	1	Front radiator assy <i>neu</i>	S 1,416.00 +
25	1	Front radiator expansion tank <i>neu</i>	S 105.00 +
26	1	Front grille assy <i>aukd</i>	S 425.00 -
27	1	Front grille chrome moulding <i>aukd</i>	S 176.00 ✓
28	1	Front left air duct vent <i>neu</i>	S 397.00 +
29	1	Front left side lower cover <i>neu</i>	S 155.00 +
			S 17,111.00
Less 5%			S 855.55
			S 16,255.45
<u>Special Nett Items</u>			
1	10	Front bumper clips <i>neu</i>	S 50.00 30
2	1	Front bumper mini logo <i>neu</i>	S 300.00 +
3	1	Front bumper mini logo <i>neu</i>	S 300.00 +
4	1	Front no plate with garnish <i>neu</i>	S 100.00 +
5	1	Front air con gas <i>neu</i>	S 120.00 50
6	1	Front radiator coolant <i>neu</i>	S 100.00 +
7	6	Front grille assy clips <i>neu</i>	S 50.00 30
			S 1,020.00
Total parts			S 17,275.45

5730

len 10%: 515

110

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLA264H Mini Copper S

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front, front left affected area and replace front and front left damaged parts.	S 1,200.00	700
2	To putty and spray painting front and front left portion.	S 1,200.00	500
3	To check wiring and focus front headlamp.	S 50.00	30
4	To remove and install front bonnet lock mechanism.	S 80.00	+
5	To remove and install front cooling system.	S 480.00	+
6	To remove and install air con system.	S 180.00	80
7	To apply anti rust proofing to front affected area.	S 140.00	40
8	Towing service.	S 100.00	60
Total labour :		S 3,130.00	12410

Total parts : \$ 17,275.45

Total labour : \$ 3,130.00

Total repair cost : \$ 20,405.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L;
L/S. 17/10/22

OS Days

Colled: 6677

L/S: \$3K

\$3K