

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTHL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057**Our File No:** CS/HLA22010094/ENY3E2**Date:** 08/11/2022**REFERENCE**

Insured/Claimant:	LIM CHWEE MENG	Policy No:	MP314637		
Date of Loss:	10/10/2022	Nature of Claim:	OD	Claim No:	MPC03751/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH2982T		
Make & Model:	BMW 216D, 1.5 (A)	Engine No:	31729601B37C15A
Reg. Date:	28/10/2016 (Man. Year: 2016)	Chassis No:	WBA2E320905B45212
Colour:	Silver	Odometer:	86175 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,437.31	2,437.31	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	380.00	300.00	44.12
Paintwork Labour	300.00	300.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,417.31	3,117.31	300.00	8.78
Approved Total (Overridden) (S\$)		2,500.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	3,417.31	1,900.00	1,517.31	44.40
+ GST 7.00/7.00% (S\$)	239.21	133.00	106.21	44.40
Nett Amount (S\$)	3,656.52	2,033.00	1,623.52	44.40

INSPECTION

Date of Assignment:	12/10/2022	Present Location:	Accord Auto Services Pte Ltd (HQ)
Date Inspected:	14/10/2022	Inspected At:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
Parts: 143	BMW 216D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH2982T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*RH SIDE MIRROR ASSY (WCP)	Broken	1,441.25 F	*1,441.25 F	
Supplementary #1							
2	1		*FRONT RH DOOR (WCP)	Dented	850.00 F	*850.00 F	
3	1		*FRONT RH DOOR TRIM BOARD CLIPS (WCP)	Necessary	30.00 F	*30.00 F	
					Sub Total (S\$)	2,321.25	2,321.25
					+ Margin on L,N Items 5.00/5.00% (S\$)	116.06	116.06
					Total Parts (S\$)	2,437.31	2,437.31

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Spray Painting Front RH Door & Mirror Cover	New	300.00	300.00
<u>Labour Items</u>				
2	To Remove/ Replace RH Side Mirror Assy & Repair Front RH Door	New	500.00	300.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	To Remove/Refix Door Trim Board , Window Glass & Necessary Mechanism	New	180.00	80.00
			Gross Labour Cost (S\$)	980.00
				680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >