

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: **HL Assurance Pte Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MP314637	Date of Loss:	10/10/2022
Vehicle Reg. No.:	SLH2982T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM CHWEE MENG	Contact No:	+6598427996
Make/Model:	BMW 216D, 1.5 (A)	Vehicle Reg. Date:	28/10/2016
Vehicle Colour:	Silver	Chassis No:	WBA2E320905B45212
Engine No:	31729601B37C15A		
Odometer:	86152 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 3

Present Location: **ACCORD AUTO SERVICES PTE LTD (HQ)**

COST OF CLAIMS	Amount
Parts	1,513.31
Miscellaneous Items	0.00
Labour	500.00
Paintwork Labour	300.00
Towing	0.00
Gross Total (S\$)	2,313.31
+ GST 7.00% (S\$)	161.93
Nett Amount (S\$)	2,475.24

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts: 143 BMW 216D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)

Print Code: **Accord Auto Services Pte Ltd/SLH2982T/11/10/2022 09:13**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*RH SIDE MIRROR ASSY / BR	0.00	0.00	*1,441.25 F	
						Sub Total (\$\$)	1,441.25
						+ Margin on L,N Items 5.00% (\$\$)	72.06
						Total Parts (\$\$)	1,513.31 ✓

F=Franchise part.

Accord Auto Services Pte Ltd/SLH2982T/11/10/2022 09:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
 new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Spray Painting Front RH Door & Mirror Cover	New	175 300.00 /
Labour Items			
2	To Remove/ Replace RH Side Mirror Assy & Repair Front RH Door	New	300 500.00
Gross Labour Cost (\$\$)			800.00

600

Accord Auto Services Pte Ltd/SLH2982T/11/10/2022 09:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS
 < END OF ESTIMATES >

2113.31

supp - 1004

3117.31

Steve (LKK)
 14/10/22, 12.12.22

OO- L1 AL
 EXCEN - ?

L/S

by AL y
 3 dep

L/S - 2493.84
 = 2500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: