

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLH 2982T Yr Regn: 98/10/16
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 210 c.c. 1196
 Colour: Silver A/C: Insured / Std / Nil / NA
 Sp. Reading: 86175 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: WBAJE 370905B 05912
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R17
 R: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 10/10/22 D.O.I. 14/10/22
 Survey held at Accord Auto
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-73K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Lump Sum / L.B.K. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____
 Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Prices _____
 Others _____
 TOTAL _____

INSURER: **HL Assurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (Own Damage)	Ref. No:
Policy No: MP314637	Date of Loss: 10/10/2022
Vehicle Reg. No.: SLH2982T	Driveable?
Driver Age/Info:	Party At Fault: UNKNOWN
TP Injury Involved? NO	Third Party Involved? YES
Insured/Claimant: LIM CHWEE MENG	Contact No: +6598427996
Make/Model: BMW 216D, 1.5 (A)	Vehicle Reg. Date: 28/10/2016
Vehicle Colour: Silver	Chassis No: WBA2E320905B45212
Engine No: 31729601B37C15A	
Odometer: 86152 KM	

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 3

Present Location: **ACCORD AUTO SERVICES PTE LTD (HQ)**

COST OF CLAIMS	Amount
Parts	1,513.31
Miscellaneous Items	0.00
Labour	500.00
Paintwork Labour	300.00
Towing	0.00
Gross Total (S\$)	2,313.31
+ GST 7.00% (S\$)	161.93
Nett Amount (S\$)	2,475.24

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts: 143 BMW 216D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: **Accord Auto Services Pte Ltd/SLH2982T/11/10/2022 09:13**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*RH SIDE MIRROR ASSY / BR	0.00	0.00	*1,441.25 F	
						Sub Total (\$\$)	1,441.25
						+ Margin on L,N Items 5.00% (\$\$)	72.06
						Total Parts (\$\$)	1,513.31

Accord Auto Services Pte Ltd/SLH2982T/11/10/2022 09:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

on Miscellaneous Items
 new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Spray Painting Front RH Door & Mirror Cover	New	115 300.00 /
Labour Items			
2	To Remove/ Replace RH Side Mirror Assy & Repair Front RH Door	New	300 500.00
Gross Labour Cost (\$)			800.00

Accord Auto Services Pte Ltd/SLH2982T/11/10/2022 09:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
 14/10/22, 10.11.22
 OO- L1 AL
 EXCER - ?
 L/S
 by AL y
 3 dep

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: