

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0884/2022/EQ
DATE : 13-Oct-22
WIP : 45903

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/10/2022
YOUR INSURED VEH NO : SMJ 6719 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MS WONG TAN CHENG
ADDRESS : 60 TREVOSE CRESCENT
#03-29
SINGAPORE 298090
TELEPHONE : HP +65 96208260
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : **SFA 6188 B**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 24/10/2016
ENGINE NO : CVN 020553
CHASSIS NO : WAUZZZF43HA047070
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Oct-22
PLACE OF ACCIDENT : HOLLAND ROADS TOWARDS FARRER ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFA 6188 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	7 X NN
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	1000 ✓
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND REAR END PANELLING.	\$	3,000.00	1100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	9,432.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFA 6188 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER ✓ <i>cc</i>	1	\$ 2,609.00	2,087.20
2	REAR BUMPER FIXING PARTS X <i>nn</i>	1	\$ 480.00	
3	REAR BUMPER SECURING STRIP - <i>mc</i>	1	\$ 249.00	198.80
4	REAR BUMPER SPOILER ✓ <i>cut</i>	1	\$ 276.00	220.80
5	REAR BUMPER REFLECTOR - LH / RH < <i>cut</i> <i>nn</i>	2	\$ 92.00	36.48
6	REAR OUTER TAIL LIGHT - LH / RH ? X <i>nn</i>	2	\$ 2,270.00	
7	REAR OUTER TAIL LIGHT TRIM - LH / RH ? X <i>nn</i>	2	\$ 68.00	
8	REAR INNER TAIL LIGHT - LH / RH ? X <i>nn</i>	2	\$ 2,270.00	
9	REAR INNER TAIL LIGHT TRIM - LH / RH ? X <i>nn</i>	2	\$ 68.00	
10	REAR LICENCE PLATE LIGHT - LH / RH X <i>nn</i>	2	\$ 128.00	
11	REAR BUMPER REINFORCEMENT BEAM ✓ <i>BT</i>	1	\$ 1,131.00	904.80
12	REAR BUMPER IMPACT BAR GASKET - LH / RH ? X <i>nn</i>	2	\$ 32.00	
13	REAR BUMPER GUIDE SECTION - LH / RH X <i>nn</i>	2	\$ 52.00	
14	REAR PARKING AID SENSOR - INNER / OUTER ? X <i>nn</i>	2	\$ 531.00	
15	REAR PARKING AID SEAL RING ✓ <i>mc</i>	4	\$ 10.00	8.00
16	REAR LID ✓ <i>mc</i>	1	\$ 3,497.00	2,797.60
17	REAR LID HINGE - LH / RH X	2	\$ 510.00	
18	REAR LID LOCK X	1	\$ 218.00	
19	REAR LID LOCK COVER X	1	\$ 8.00	
20	REAR LID ATTACHMENT PARTS X <i>nn</i>	1	\$ 429.00	
SUB TOTAL SPARE PARTS		:	\$ 14,928.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFA 6188 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK ACTUATOR PUSH BUTTON X	1	\$ 1,478.00	
22	REAR LID LOCK STRIKER X	1	\$ 37.00	
23	REAR LID FLAP GASKET X	1	\$ 229.00	
24	PACKING ADHESIVE / Sma	1	\$ 21.00	16.80
25	AUDI EMBLEM /	1	\$ 144.00	114.80
26	REAR CROSS PANEL ? X NN	1	\$ 274.00	
27	REAR CROSS PANEL REINFORCEMENT ? X NN	1	\$ 532.00	
28	REAR CROSS PANEL TRIM ? X NN	1	\$ 185.00	
29	REAR NO PLATE / BT	S/N	\$ 60.00	60.00
30	ACRYLIC SEALANT ? X NN	S/N	\$ 180.00	
31	CAVITY WAX ? X NN	S/N	\$ 140.00	
32	STONE CHIP ? X NN	S/N	\$ 180.00	
33	METAL FILLER POWDER ? X NN	S/N	\$ 280.00	
34	SUNDRIES ? ✓ NEC		\$ 400.00	31.52
TOTAL SPARE PARTS		:	\$ 19,068.00	
TOTAL LABOUR CHARGES		:	\$ 9,432.00	
GRAND TOTAL		:	\$ 28,500.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Lim Qian
18/10/2022
Before paint photos.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

4 Days.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged parts) during resurvey
- Parts price information
- To provide a "No Fault Prejudice" basis
- To provide a "No Fault Prejudice" basis
- To provide a "No Fault Prejudice" basis
- To provide a "No Fault Prejudice" basis

Acknowledged by: _____
Signature: _____
Date: _____