

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SJR 4259 G

Chassis No: JMYSRCY2A9U004290

Make/Model : MITSUBISHI LANCER

Accident date : 01.10.2022

TP Chinn-
Version-

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear fender <i>Perk</i>	1	\$ 690.80 <i>X.</i>
2	Rear bumper <i>Debond</i>	1	\$ 1,800.00 <i>850 (sn)</i>
3	Rear bumper side holder @ \$44.00 <i>RH New</i>	2	\$ 88.00 <i>44.</i>
	<i>44 SN: 850</i>		\$ 2,578.80
	<i>3460</i>	Less 20% Disc	\$ 515.76
		Total	\$ 2,063.04

Special Nett Items

1	Rear RH sport rim <i>cut</i>	1	\$ 800.00 <i>400</i>
2	Rear RH tyre <i>new</i>	1	\$ 300.00 <i>X.</i>
	<i>400</i>	Total	\$ 1,100.00

Labour Cost

1	Remove & reinstall reverse sensor		\$ 150.00 <i>50</i>
2	Remove & reinstall bootlid inner garnish	<i>650</i>	\$ 100.00 <i>X</i>
3	Remove ,replace & repair consistent to the accident		\$ 900.00 <i>200</i>
4	Respray painting		\$ 1,000.00 <i>400.</i>
	Total		\$ 2,150.00

Grand Total \$ 5,313.04 5570.92

total: 1833.60

L/S: 1.5K.

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: