

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22010103/GPA3Q2**Date:** 16/01/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000567035-01
Claimant Vehicle No :	SKS8399S	Insured Vehicle No :	SKW7440R
Date of Loss:	10/10/2022	Nature of Claim:	TP
			Claim No: 202222003780

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS8399S		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC33524
Reg. Date:	30/07/2020 (Man. Year: 2019)	Chassis No:	WAUZZZGA7KA084781
Colour:	White	Odometer:	12043 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,742.00	418.00	5,324.00	92.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,472.00	2,592.00	1,880.00	42.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,214.00	3,010.00	7,204.00	70.53
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/10/2022		
Date Inspected:	18/10/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Jan 2023)	
Parts:	N/A	AUDI Q2 999cc 1.0 TFSI S TRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS8399S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -LH	Repair	2,962.00 FS	*- FS
2	1		*REAR OUTER DOOR SEAL -LH	Not Necessary	151.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*REAR DOOR CATCH -LH	Not Necessary	134.00 FS	*- FS
7	1		*REAR DOOR OUTER SEAL -LH	Not Necessary	66.00 FS	*- FS
8	1		*REAR DOOR COVER -LH	Cut	238.00 FS	*238.00 FS
9	1		*REAR WHEEL COVER -LH	Cut	180.00 FS	*180.00 FS
10	1		*REAR DOOR SIDE MEMBER TRIM -LH	Not Necessary	251.00 FS	*- FS
11	1		*REAR WHEEL HOUSING LINER -LH	Not Necessary	220.00 FS	*- FS
12	1		*REAR ALUMINIUM RIM	Not Necessary	1,002.00 FS	*- FS
13	1		*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,742.00	418.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	400.00	0.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR TO REPAIR LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,600.00	800.00
3	TO RESRPAY LHS REAR DOOR AND LHS REAR FENDER	New	2,000.00	1,600.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,472.00	2,592.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >