

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2210-556

DATE : 12-Oct-2022

POLICY NO. :

VEHICLE REG. NO. : SJN4516K

VEHICLE MAKE : TOYOTA / WISH 1.8 A

COE expire 2028

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de/</i>	1	\$ 780.00	\$ 780.00
2	Rear Bumper Retainer RH <i>? X nn</i>	1	\$ 100.00	\$ 100.00
3	Rear Bumper Retainer LH <i>X nn</i>	1	\$ 100.00	\$ 100.00
4	Rear Bumper Reflector RH <i>? X nn</i>	1	\$ 80.00	\$ 80.00
5	Rear Bumper Reflector LH <i>X nn</i>	1	\$ 80.00	\$ 80.00
6	Tail Lamp RH <i>ca/</i>	1	\$ 350.00	\$ 350.00
7	Tail Lamp LH <i>X nn</i>	1	\$ 350.00	\$ 350.00
8	Tailgate <i>bt/</i>	1	\$ 1,280.00	\$ 1,280.00
9	Tailgate Toyota Emblem <i>ne/</i>	1	\$ 100.00	\$ 100.00
10	Tailgate Lock <i>X nn</i>	1	\$ 150.00	\$ 150.00
11	Tailgate Rubber Seal <i>nee/</i>	1	\$ 160.00	\$ 160.00
12	Tailgate Chrome Garnish <i>X nn</i>	1	\$ 200.00	\$ 200.00
13	Tailgate Inner Trim <i>X nn</i>	1	\$ 300.00	\$ 300.00
14	Tailgate Inner Trim Handle Cover <i>X nn</i>	1	\$ 80.00	\$ 80.00
15	End Panel Garnish <i>de/</i>	1	\$ 280.00	\$ 280.00
16	End Panel <i>bt/ photo?/</i>	1	\$ 480.00	\$ 480.00
17	Spare Tyre Panel <i>X nn</i>	1	\$ 880.00	\$ 880.00
18	Exhaust Pipe <i>X nn</i>	1	\$ 480.00	\$ 480.00
19	Rear Windscreen Moulding <i>ne/</i>	4	\$ 40.00	\$ 160.00
Total Spare Parts				\$ 6,390.00
SPECIAL NETT				
20	Rear Windscreen Sealant <i>ne/</i>	1	\$ 40.00	\$ 40.00
21	Rear License Plate <i>X nn</i>	1	\$ 40.00	\$ 40.00
22	Rear Bumper Clip <i>ne/</i>	10	\$ 3.00	\$ 30.00
23	Reverse Sensor <i>an ca/</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 310.00

3590
258
2692.50

270

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2210-556
DATE : 12-Oct-2022
POLICY NO. :
VEHICLE REG. NO. : SJN4516K
VEHICLE MAKE : TOYOTA / WISH 1.8 A
COE expire 2028TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>LABOUR</u>			
24	Remove, Repair, Replace and Refit Affected Accident Area	1	\$ 800.00	\$ 800.00 700
25	Spray Paint (Rear Bumper, Tailgate, End Panel, Spare Tyre Panel, Rear Fender RH, Rear Fender LH)	1	\$ 1,200.00	\$ 1,200.00 1000
26	Transfer Tailgate Fitting, Window Mechanism to New Tailgate	1	\$ 80.00	\$ 80.00 60
27	Remove and Replace Rear Windscreen	1	\$ 120.00	\$ 120.00
28	Remove and Refit Rear Bumper Sensor	1	\$ 80.00	\$ 80.00 40
29	Remove, Refit, Realign Exhaust Pipe & Silencer	1	\$ 80.00	\$ 80.00
30	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 50.00	\$ 50.00
31	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,440.00
Amount Before Excess	\$ 9,140.00
Add GST @ 7%	639.80
Total Amount Payable	\$ 9,779.80

2000

P - 2692.50
S/N - 270.00
L - 2000.00
Suppl - 37.50
T - 5000.00
20%
4000

L/S - \$4,000/7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasa
Hp 90010068

7 days

4/5

13/10/22 @ 1700

Resurvey after repair

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

**Supplementary
Estimate**

ESTIMATE NO. : EST2210-556

DATE : 15-Oct-2022

POLICY NO. :

VEHICLE REG. NO. : **SJN4516K**

VEHICLE MAKE : TOYOTA / WISH 1.8A

TO Motor Claim Department**AXA INSURANCE SINGAPORE PTE LTD**

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Air Vent RH de 	1	\$ 50.00	\$ 50.00
Total Spare Parts				\$ 50.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
Total Labour				\$ -
Amount Before Excess				\$ 50.00
Add GST @ 7%				3.50
Total Amount Payable				\$ 53.50

Estimate prepared by: KenGuan

**50
25%
37.50**