



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EUROKARS HABITAT PTE LTD 27 LENG KEE ROAD SINGAPORE 159098			Ref: CS4/TP22010112/Evy3e2	
			Date: 02/12/2022	
			Code: TP555	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SMG 5349X
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From DALLAS YEE		Assign Date		15/09/2022
2. Vehicle Particulars & Condition				
Make & Model MINI COOPER S COUNTRYMAN		c.c		1998
Engine No. HIDDEN		Year of Reg.		2018
Chassis No. WMWYS920303G52009		Colour		BLUE
Odometer 40882 KM		Steering		IN ORDER
Brakes IN ORDER		Modification		SPORTS RIM
General GOOD				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	BRIDGESTONE	4 mm	
L/H Front Tyre	215/50 R17	BRIDGESTONE	4 mm	
R/H Rear Tyre	215/50 R17	BRIDGESTONE	4 mm	
L/H Rear Tyre	215/50 R17	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date 10/08/2022		Inspection Date 15/09/2022		
Survey held at 27A TANJONG PENJURU SINGAPORE 609042				
Repairer EUROKARS HABITAT PTE LTD				
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		