



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



Liberty Insurance Pte Ltd NO. 51 Club Street #03-00, Liberty House Singapore 069428 ATTN.: MOTOR CLAIMS FAX:		NAME: 15/9/22 ADDRESS: 14 days TEL:		WIP: 57736 EXCESS: DATE: 18-Aug-22	
VEH NO:	SMG5349X	DATE IN:		CONTACT PERSON:	STEPHANIE 63310685
CHASSIS NO:	WMWYS920303G52009	MILEAGE:		TYPE OF CLAIM:	OWN DAMAGE
MODEL:	Cooper S Countryman RHD	DATE REG.:	21-Dec-18	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description			1ST	SUPP	REVISED	PRICES
		QTY					
1	BONNET	1	M41.00.9.626.977			DD	\$ / 1,523.28
2	ADJUSTER	2	B51.76.7.183.752			nn	\$ X 15.08
3	HINGE LH	1	M41.00.7.449.379			nn	\$ X 143.13
4	HINGE RH	1	M41.00.7.449.380			nn	\$ X 143.13
5	STRIKER	2	M51.23.7.441.480			nn	\$ X 158.34
6	TRIM RING, HEADLIGHT LH	1	M51.13.7.388.117			rec	\$ / 92.89
7	TRIM RING, HEADLIGHT RH	1	M51.13.7.388.118			BR	\$ / 92.89
8	EMBLEM FRONT	1	M51.14.9.447.807			rec	\$ / 80.53
9	LABEL, COOLANT	1	M71.23.6.992.810			rec	\$ / 32.50
10	FRONT BUMPER	1	M51.11.7.478.626			BR	\$ / 876.52
11	SUPPORT FOGLAMP LH	1	M51.11.7.390.507			nn	\$ X 91.39
12	SUPPORT FOGLAMP RH	1	M51.11.7.390.508			BR	\$ / 91.39
13	C-CLIP NUT	1	B51.71.7.065.773			rec	\$ / 1.76
14	FRONT GRILLE	1	M51.13.7.405.406			BR	\$ / 284.57
15	FRONT BUMPER CENTER COVER	1	M51.11.7.405.409			BR	\$ / 312.52
16	FLAP, TOWING COVER	1	M51.11.7.478.627			mls	\$ / 57.13
17	FRONT GRILLE LOWER	1	M51.11.7.390.511			BR	\$ / 122.53
18	BUMPER SPOILER LEFT	1	M51.11.7.478.633			BR	\$ / 898.69
19	BUMPER SPOILER RIGHT	1	M51.11.7.478.634			BR	\$ / 898.69
20	BUMPER SPOILER CENTER	1	M51.11.7.405.393			BR	\$ / 188.44
21	TRIM RING FOR FOGLAMP LH	1	M51.11.7.479.127			nn	\$ X 67.80
22	TRIM RING FOR FOGLAMP RH	1	M51.11.7.479.128			BR	\$ / 67.80
23	FOGLAMP TRIM RING BRACKET LH	1	M51.11.7.390.551			nn	\$ X 81.19
24	FOGLAMP TRIM RING BRACKET RH	1	M51.11.7.390.514			BR	\$ / 115.25
25	RIVET	14	M07.14.9.807.127			rec	\$ / 10.08
26	EXPANDING RIVET	2	M51.11.1.908.077			rec	\$ / 1.30
27	FRONT BUMPER REINFORCEMENT	1	M51.11.7.378.727			BT	\$ / 486.65
28	FRONT BUMPER SPONGE	1	M51.64.7.378.723			BR	\$ / 68.83
29	REINFORCEMENT BRACKET LH	1	B51.11.7.406.387			BR	\$ / 135.66
30	REINFORCEMENT BRACKET RH	1	B51.11.7.406.388			BR	\$ / 135.66

1	CROSSLINK, FRONT LOWER	1	B51.11.7.301.605			BT	\$ /	149.31
32	FRONT BUMPER LOWER REINFORCEMENT	1	M51.11.7.378.735			BT	\$ /	189.47
33	LOWER REINFORCEMENT BRACKET LH	1	M51.11.7.378.739			BT	\$ /	111.22
34	LOWER REINFORCEMENT BRACKET RH	1	M51.11.7.378.740			BT	\$ /	111.22
35	ADAPTER, LOWER LH	1	B51.64.7.302.535			BT	\$ /	132.99
36	ADAPTER, LOWER RH	1	B51.11.7.301.604			BT	\$ /	106.73
37	VERTICAL BRACE LH	1	B51.11.7.301.585			nn	\$ X	64.35
38	VERTICAL BRACE RH	1	M51.11.7.498.085			BT	\$ /	64.35
39	BLIND RIVET	4	B07.14.6.984.985			nec	\$ /	4.96
40	RADIATOR AIRDUCT	1	M51.74.7.390.474			BR	\$ /	287.04
41	SIDE SKIRT LH	1	M51.77.7.467.695			nn	\$ X	375.25
42	SIDE SKIRT RH	1	M51.77.7.467.696			BR	\$ /	375.25
43	FRONT ENTRANCE COVER LH & RH	2	M51.77.7.389.353			BR	\$ /	296.40
44	REAR LEFT ENTRANCE COVER	1	M51.77.7.406.371			nn	\$ X	111.22
45	REAR RIGHT ENTRANCE COVER	1	M51.77.7.406.372			BR	\$ /	111.22
46	CLIP NATURE	14	B51.43.7.001.491			nec	\$ /	15.54
47	LEFT DOOR SILL LH	1	M51.77.7.411.085			TN	\$ /	447.72
48	RIGHT DOOR SILL RH	1	M51.77.7.411.086			TN	\$ /	447.72
49	CLIP, UPPER	8	M51.71.7.048.316			nec	\$ /	11.44
50	CLIP, BOTTOM	8	M07.14.7.222.908			nec	\$ /	17.20
51	C-CLIP	6	B07.14.7.311.312			nec	\$ /	8.58
52	ADAPTER FOR FENDER RH	1	M51.77.7.410.644			nec	\$ /	32.76
53	FRONT FENDER RH	1	M41.00.7.449.378			DD	\$ /	635.96
54	FENDER BRACKET RH	1	M41.00.7.449.388			nn	\$ X	81.19
55	BRACKET FOR GAS SPRING RH	1	M41.00.7.438.912			nn	\$ X	58.24
56	FRONT FENDER ARCH LH	1	M51.77.7.475.349			CH	\$ /	197.73
57	FRONT FENDER ARCH RH	1	M51.77.7.475.350			BR	\$ /	197.73
58	FRONT FENDER UNDERSHIELD LH	1	M51.71.7.386.956			nn	\$ X	169.97
59	FRONT FENDER UNDERSHIELD RH	1	M51.71.7.387.865			BR	\$ /	169.97
60	EXPANDING NUT	12	B07.14.7.201.307			nec	\$ /	13.32
61	FRONT FENDER RH COVER TRIM (FLAG)	1	M51.13.2.413.351			nec	\$ /	443.88
62	FRONT FENDER LIGHT RH	1	M63.13.7.406.370			nn	\$ X	69.68
63	TRIM FOR FENDER LIGHT RH	1	M51.13.7.414.096			BR	\$ /	108.22
64	A-PILLAR COVER RH	1	M51.13.7.390.102			nn	\$ X	134.03
65	FRONT DOOR OUTER MOULDING RH	1	M51.33.7.390.100			nn	\$ X	87.23
66	CHARGE-AIR COOLER	1	B17.51.7.617.598			BT	\$ /	855.92
67	BRACKET LOWER FOR INTERCOOLER	2	B17.11.8.617.880			nec	\$ /	68.76
68	V-BRACE	1	B51.64.7.434.550			BT	\$ /	168.35
69	HEADLIGHT, LH	1	M63.11.7.441.315			nn	\$ X	3,362.45
70	HEADLIGHT RH	1	M63.11.7.441.316			BR	\$ /	3,362.45
71	FOGLAMP LH	1	M63.17.7.409.121			nn	\$ X	580.84
72	FOGLAMP RH	1	M63.17.7.409.122			BR	\$ /	580.84
73	ALIGNMENT ELEMENT	3	M07.14.9.310.339			nec	\$ 35.70	111.40
74	MOUNT FOR HEADLIGHT RH	1	M51.64.7.378.746			BR	\$ /	292.76
75	CLIP	1	M51.11.7.490.268			nec	\$ /	4.88
76	RH F56 U/J MIRROR COVER	1	M51.16.2.409.444			BR	\$ /	259.74
77	BONNET SEAL	1	M51.76.7.388.091			nn	\$ X	42.70

	HEADLIGHT LOWER GASKET RH	2	M51.76.7.388.099		nn	\$ X	75.40
79	UNDERBODY PANEL COVER RH	1	B51.75.7.290.804		BR	\$ /	104.91
80	UNDERBODY PANEL COVER LH	1	B51.75.7.290.803		nn	\$ X	104.91
81	UNDERBODY PANEL COVER REAR RH	1	M51.75.7.386.952		nn	\$ X	100.23
82	UNDERBODY PANEL COVER REAR LH	1	M51.75.7.386.951		nn	\$ X	128.90
83	REAR DOOR OUTER TRIM LH	1	M51.77.7.389.363		BR	\$ /	153.59
84	REAR DOOR OUTER TRIM RH	1	M51.77.7.389.364		BR	\$ /	153.59
85	WASHER TANK	1	B61.66.7.403.903		CR4	\$ /	177.84
86	WASHER MOTOR	1	B67.12.7.388.349		nn	\$ X	152.10
87	FILLER PIPE	1	M61.66.7.380.744		nn	\$ X	62.92
88	COVER F FILL	1	B61.66.7.375.587		nn	\$ X	15.34
89	MOUNT FOR WASHER TANK	1	B51.64.7.318.491		REC	\$ /	32.44
90	SUPPORT FOR BUMPER	2	B51.11.7.424.511		nn	\$ X	33.28
91	FRONT SUBFRAME	1	B31.11.6.872.729		BT	\$ /	1,935.96
92	ASA-BOLT	8	B07.14.6.888.411		REC	\$ /	92.56
93	SQUARE NUT	4	B31.10.6.867.397		REC	\$ /	34.84
94	ASA-BOLT	4	B31.10.6.868.038		REC	\$ /	53.56
95	HEX BOLT	2	B07.11.9.908.020		REC	\$ /	15.34
96	LOWER ARM LH	1	M31.12.6.879.843		nn	\$ X	377.58
97	LOWER ARM RH	1	M31.12.6.879.844		BT	\$ /	377.58
98	BRACKET WITH RUBBER FOR LOWER ARM LH	1	B31.12.8.831.645		nn	\$ X	253.31
99	ASA SCREW, S	4	M31.10.6.862.545		REC	\$ /	36.40
100	B31.10.6.863.102/ASA SCREW, S	2	B07.14.8.836.182		REC	\$ /	19.64
101	ASA SCREW, S	2	M33.30.6.857.402		REC	\$ /	16.52
102	BRACKET WITH RUBBER FOR LOWER ARM RH	1	B31.12.8.831.646		BT	\$ /	253.31
103	FRONT RIGHT SHOCK ABSORBER	1	M31.31.6.867.212		BT	\$ /	390.39
104	LEFT FRONT SHOCK ABSORBER	1	M31.31.6.867.211		BT	\$ /	390.39
105	KNUCKLE ARM LH	1	B31.21.6.876.645		BT	\$ /	668.07
106	KNUCKLE ARM RH	1	B31.21.6.876.646		BT	\$ /	668.07
107	HEXAGON SCREW	2	B31.30.6.798.530		REC	\$ /	18.46
108	HEX NUT	2	B07.11.9.905.032		REC	\$ /	6.24
109	WHEEL HUB WITH BEARING	2	B31.20.6.874.443		REC	\$ /	1,349.40
110	ROUND COLLAR	16	B31.20.6.872.920		REC	\$ /	167.52
111	COLLAR SCREW	2	B33.40.6.858.534		REC	\$ /	51.48
112	SPEED SENSOR LH & RH	2 / (RH)	B34.52.6.895.881		BR	\$ 299.65	599.30
113	ISA SCREW	2	C07.12.9.904.588		REC	\$ /	8.84
114	BRACKET FOR FOR BRAKE HOSE FRONT LH	1	B34.30.6.854.967		nn	\$ X	31.72
115	BRACKET FOR FOR BRAKE HOSE FRONT RH	2	B34.30.6.854.968		BT	\$ /	60.32
116	ASA-BOLT	2	B31.10.6.876.027		REC	\$ /	25.62
117	HEX NUT WIHT	2	M33.30.6.760.587		REC	\$ /	5.98
118	CABLE CLAMP	2	C32.73.1.465.257		REC	\$ /	9.62
119	STABILIZER BAR	1	B31.30.6.853.911		BT	\$ /	445.44
120	STABILIZER SUPPORT BUSHING	2	B33.50.6.861.149		REC	\$ /	67.74
121	HEX BOLT	4	B07.11.9.908.084		REC	\$ /	13.28
122	FRONT STABILIZER LINK	2 / (RH)	B31.30.6.862.864		BT	\$ 138.71	277.42
123	HEXAGON NUT	16	M33.32.6.768.884		REC	\$ /	52.00
124	SHOCK TOP MOUNTING RH & LH	2	B31.33.6.892.617		BT	\$ /	620.10

5	HEX BOLT WIT	11	B31.30.6.869.931		hec	\$ /	80.85
126	NUT	10	M33.32.6.760.668		hec	\$ /	32.50
127	COVERING CAP	2	B31.30.6.864.550		hec	\$ /	24.70
128	SPRING PAD LOWER	2 (RH)	B31.33.6.860.788		hec	\$ 19.44 /	38.88
129	SPRING PAD UPPER	2 (RH)	B31.31.6.860.787		hec	\$ 27.17 /	54.34
130	ADDITIONAL DAMPER	2 (RH)	B31.33.6.858.239		hec	\$ 55.19 /	110.38
131	FRONT COIL SPRING	2 (RH)	B31.33.6.872.339		BT	\$ 334.30 /	668.60
132	DRIVESHAFT LH	1	B31.60.5.A2E.055		nn	\$ X	2,535.52
133	O-RING	1	B24.27.8.650.203		hec	\$ /	10.46
134	SHAFT SEAL	1	B24.27.8.647.245		nn	\$ X	57.13
135	DRIVESHAFT RH	1	B31.60.5.A2E.056		BT	\$ /	2,535.52
136	SHAFT SEAL,	1	B23.11.8.651.159		hec	\$ /	52.39
137	LEVEL SENSOR LH & RH	2 (RH)	B37.14.6.870.200		BR	\$ 220 /	440.00
138	BRACKET, LEVEL SENSOR LH & RH	2 (RH)	B37.14.6.872.824		BR	\$ 22.45 /	44.90
139	CNTROL ROD,	1	B37.14.6.854.697		hec	\$ /	23.53
140	HEXAGON SCREW	2 (RH)	B37.14.6.869.771		hec	\$ 4.49 /	8.98
141	ISA SCREW	2 (RH)	B07.12.9.904.491		hec	\$ 3.45 /	6.90
142	HEX NUT	2 (RH)	B07.12.9.905.817		hec	\$ 7.78 /	14.56
143	SELF-LOCKING	2 (RH)	B07.14.7.575.163		hec	\$ 1.43 /	2.86
144	STEERING GEAR	1	B32.10.5.A39.022		BT	\$ /	6,181.82
145	PRESTOL-CAGE	4	B37.14.6.850.307		hec	\$ /	21.32
146	GASKET, BULK	1	B32.10.6.889.834		hec	\$ /	23.20
147	BRAKE PADS	1	M34.10.6.860.019		nn	\$ X	460.59
148	BRAKE PAD SENSOR RH	1	M34.35.6.888.167		CHT	\$ /	68.12
149	BRAKE DISC, FRT RH & LH	2 (RH)	B34.11.6.865.713		BR	\$ 385.13 /	770.26
150	BOLT	2	B34.21.1.161.806		nn	\$ X	5.34
151	BRAKE PAD PASTE	2	M83.19.2.158.851		nn	\$ X	3.90
152	TORX SCREW W	4	M34.10.6.864.424		nn	\$ X	45.52
153	HEX BOLT	2	M34.11.6.768.190		nn	\$ X	20.02
154	CALIPER HOUSING	1	B34.11.6.860.268		BT	\$ /	868.73
155	VALVE BLEEDER	1	M34.11.6.768.188		nn	\$ X	12.54
156	REPAIR KIT BELLOWS FOR BRAKE	1	B34.20.7.848.324		nn	\$ X	42.19
157	REPAIR SET B	1	B34.10.6.867.316		nn	\$ X	34.77
158	CALLIPER CARRIER RH	1	B34.11.6.867.312		nn	\$ X	424.90
159	BACKPLATE RH	1	B34.10.6.854.970		BT	\$ /	103.28
160	HEX BOLT	3	B34.11.6.868.785		nn	\$ X	5.85
161	BRAKE HOSE FRONT RH	1	B34.30.6.894.453		CHT	\$ /	67.02
162	BRAKE PIPE	1	B34.30.6.872.769		BT	\$ /	54.92
163	CLIP	1	M34.34.1.163.565		hec	\$ /	2.21
164	WIRE CLIP, S	1	B34.30.6.858.577		hec	\$ /	3.71
165	CABLE CLIP	1	B34.35.6.767.984		hec	\$ /	1.24
166	WIRING CLIP,	1	B34.30.6.858.580		hec	\$ /	4.81
167	SPACER, 4-WA	1	B34.32.6.777.692		hec	\$ /	1.17
168	ENGINE MOUNT UPPER	1	B22.11.8.835.566		TI	\$ /	327.67
169	ASA-BOLT	1	B22.11.6.858.061		nn	\$ X	9.69
170	TORX SCREW,	1	M07.12.9.908.650		nn	\$ X	9.62
171	ENGINE MOUNTING LOWER	1	B22.11.6.885.788		nn	\$ X	100.36

2	GEARBOX MOUNTING	1	B22.31.6.853.449		nn	\$ X	284.89
73	REAR AXLE	1	B33.30.6.851.560		BT	\$ /	2,091.96
174	SCREW SELF-TAPPING	4	B33.30.6.857.401		nn	\$ X	62.68
175	CROSS BRACE	1	M33.30.6.859.708		nn	\$ X	31.79
176	SCREW	2	B07.11.9.908.596		nn	\$ X	10.40
177	TRAILING ARM LH	1	B33.30.8.842.879		nn	\$ X	1,318.59
178	TRAILING ARM RH	1	B33.30.8.842.880		BT	\$ /	1,318.59
179	RUBBER MOUNTING FOR TRAILING ARM	2	B33.32.6.864.237		nn	\$ X	123.12
180	INSTALLATION	2	B83.19.2.405.829		nn	\$ X	102.96
181	BRACKET, TRAILING ARM LH	1	M33.32.6.896.991		nn	\$ X	86.91
182	BRACKET, TRAILING ARM RH	1	M33.32.6.896.992		nn	\$ X	86.91
183	MULTI-PURPOSE BOLT	6	B31.10.6.885.162		nn	\$ X	58.50
184	WISHBONE, TOP LH & RH	2	M33.32.6.884.693		nn	\$ X	666.00
185	WISHBONE, LOWER LH & RH	2 (RH)	B33.32.6.851.569		BT	\$ 333	666.00
186	ASA BOLT	2	B33.32.6.858.053		nec	\$ /	21.58
187	ECCENTRIC BOLT	2	B33.32.6.858.054		nec	\$ /	30.94
188	ECCENTRIC FLANGE	2	M33.30.6.786.186		nec	\$ /	14.82
189	REAR COIL SPRING	2	B33.53.6.866.775		nn	\$ X	717.60
190	STABILIZER BAR REAR	1	B33.50.6.853.923		nn	\$ X	475.54
191	REAR STABILIZER LINK LH & RH	2	B33.50.6.862.865		nn	\$ X	227.24
192	STAR-SOCKET	6	B07.11.9.908.026		nn	\$ X	17.16
193	SHOCK ABSORB REAR LH & RH	2 (RH)	M33.52.6.888.423		BT	\$ 255.04	511.68
194	HEX NUT WIHT	6	B07.11.9.907.135		nn	\$ X	19.92
195	REAR SHOCK ABSORBER MOUNTING LH & RH	2 (RH)	B33.50.6.791.706		nec	\$ 180.05	360.10
196	CONICAL RING	2	B33.50.6.864.789		nn	\$ X	50.18
197	TORX SCREW W	6	B07.11.9.907.137		nn	\$ X	17.58
198	COVERING CAP	2	B33.50.6.863.445		nn	\$ X	10.80
199	SPRING PAD UPPER	2	B33.53.6.875.113		nn	\$ X	37.32
200	SPRING PAD LOWER	2	B33.53.6.871.665		nn	\$ X	32.24
201	TORX SCREW W	2	M33.52.6.858.060		nn	\$ X	33.02
202	AUXILIARY DAMPER	2	M33.53.6.852.453		nn	\$ X	111.42
203	CONTROL ROD,	2	B37.14.6.853.713		nn	\$ X	40.56
204	DISC WHEEL	4	M36.11.6.856.032		CUT	\$ /	4,802.48
205	RUBBER VALVE	4	B36.12.1.116.326		nec	\$ /	149.76
206	VALVE	4	B36.14.1.095.389		nec	\$ /	26.80
207	FRONT BUMPER SENSOR	3	B66.20.9.274.428		BR	\$ 990.05	2,311.89
208	SENSOR GASKET	6	B66.20.9.283.203		nec	\$ /	41.34
209	FENDER SENSOR	2	B66.20.9.274.429		BR	\$ /	660.52
210	OIL LEVEL SENSOR	1	M12.61.8.638.754		BR	\$ /	458.51
211		0	0			\$	-
TOTAL PARTS						\$	67,964.32
TOTAL PARTS COST						\$	67,964.32

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							

TOTAL LABOUR			\$ -	\$ 21,080.00
TOTAL PARTS			\$ -	\$ 67,964.32
TOTAL			\$ -	\$ 89,044.32
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	\$ -
GST 7%			\$ -	\$ -

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
SUPPLEMENTARY ITEMS



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
SUPPLEMENTARY ITEMS 2

EUROKARS GROUP

Liberty Insurance Pte Ltd NO. 51 Club Street #03-00, Liberty House Singapore 069428 ATTN.: MOTOR CLAIMS FAX:		NAME: ADDRESS: TEL:		WIP: 57736 EXCESS: DATE: 1-Nov-22	
VEH NO:	SMG5349X	DATE IN:		CONTACT PERSON:	STEPHANIE 63310686
CHASSIS NO:	WMWYS920303G52009	MILEAGE:		TYPE OF CLAIM:	OWN DAMAGE
MODEL:	Cooper S Countryman RHD	DATE REG.:	21-Dec-18	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description		REVISED	PRICES
	QTY			
1	SET OF CABLE FOR FRONT BUMPER	1 M61.12.8.715.611	TN	\$ / 309.27
2	ENGINE UNDERCOVER CENTER	1 M51.75.7.402.947	m/s	\$ / 167.51
3	BRAKE FLUID	4 B83.13.2.405.977	NEC	\$ / 135.20
4	BALL JOINT FRONT RH	1 B32.10.5.A01.8D4	BSJ	\$ / 172.77
5	RIVET	14 M07.14.9.807.127	NEC	\$ / 10.08
6		0 0		\$
TOTAL PARTS				\$ 794.83
				\$ -
TOTAL PARTS COST				\$ 794.83
<u>Labour Description</u>				
1	TO CONDUCT & PERFORM BRAKE TEST ON THE VEHICLE		4-20 ✓	\$ 840.00
TOTAL LABOUR			\$ -	\$ 840.00
TOTAL PARTS			\$ -	\$ 794.83
TOTAL			\$ -	\$ 1,634.83
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.