



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881			Ref: CS/LAW22010113/Tny3e2 Date: 31/01/2023 Code: L021	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	YM 3098J	Veh. Inspected	FBR 2951Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CF.clm.1760.21-iii	Excess (\$)	0.00	
Assign From	SAMANTHA CHEW	Assign Date	15/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA AEROX	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MH3SG4640LJ071085	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80 R14	IRC	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R14	IRC	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	16/01/2021	Inspection Date	12/10/2022	
Survey held at	BIKES AND TEA PTE LTD 25 KAKI BUKIT ROAD 4, #01-43, SYNERGY @ KB, SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	