



FORMTEAM ADJUSTERS PTE LTD

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

Co.Reg No: 201212134W

GST Reg No: 201212134W

Our Reference : FTA/III/2106/19416

Your Reference: MCV2021D0000280

Date : 01-Jul-2021

Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #05-01
IOB Building
Singapore 049711

Attention : Ms Carine Kek

Dear Sir/Mdm,

PAPER RE-INSPECTION OF VEHICLE NO . FBR 2951Z

Pursuant to your instructions on 16-Jun-2021 , we have conducted a paper reinspection of the above vehicle.

We recommend a repair cost of **\$1,350.00** (see report) based on lump sum repair and the estimated duration of repairs would take **04 days** .

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Adjusters Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)

Bryan Teng
Automobile Appraiser

(Email : bryan@fta.com.sg)

Encl. Re-inspection Report

AUTOMOBILE ASSESSMENT REPORT**PAGE : 1**Our Reference : FTA/III/2106/19416Your Reference : MCV2021D0000280

Date : 01-Jul-2021

Attention : Ms Carine Kek

TO : Motor Claims Department
 India International Insurance Pte Ltd
 64 Cecil Street #05-01
 IOB Building
 Singapore 049711

Dear Sir/Madam,

Vehicle No : FBR 2951Z
 Model : Yamaha Aerox GDR155A
 Mileage : -
 Chassis No : MH3SG4640LJ071085
 Workshop : M/S Project 8 Motorworks

Pursuant to your instructions on **16-Jun-2021**, we have conducted a paper reinspection of the above vehicle.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Cover Handle Upper	Not Necessary		-	-
1	Handle Bar Complete	Not Necessary		120.00	-
1 set	Handle Bar Balancer (End Grips)	N/S Cut		60.00	60.00
1 set	Wind Mirror	N/S Cut		120.00	70.00
1	Brake Lever RH	Cut		48.00	48.00
1	Front Centre Panel	Usable		-	-
1	Headlamp Cowling LH	Cut		167.50	167.50
1	Headlamp Assy (LED)	Not Necessary		685.00	-
1	Front Signal LH	Not Necessary		86.00	-
2	Front Fork	Not Necessary		820.00	-
1	Front Mudguard	Cut		110.00	90.00
1	Foot Board LH	Cut		186.50	186.50
1	Footrest Board Lower Side Cover	Cut		128.60	128.60
1	Rear Mudguard	Deformed		158.60	158.60
1	Crankcase Cover	Cut		285.00	230.00

FORMTEAM ADJUSTERS PTE LTD

PAGE : 2

Our Reference : FTA/III/2106/19416

Your Reference : MCV2021D0000280

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Muffler Protector	Deformed		110.00	110.00
	Sub-Total			3,085.20	1,249.20
	Discount Percentage 10%			308.52	124.92
	Total Parts List Items			2,776.68	1,124.28
	<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>				
1	ERP IU Unit	Cut		160.00	160.00
1	Steering Cone Bearing	Necessary		120.00	70.00
1	Body Sticker	Not Fitted		150.00	-
1	Rear Box	Cut		280.00	220.00
1	Rear Box Rack With Base	Refit		150.00	-
	Total Parts Special Nett Items			860.00	450.00
	Total Parts			3,636.68	1,574.28

Our Reference : FTA/III/2106/19416Your Reference: MCV2021D0000280

QTY	DESCRIPTION	SUBMITTED	REVISED
	<u>LABOUR & MISC</u>		
1	Towing (2 trips).	120.00	-
2	Steering stem repair & align.	150.00	-
3	Chassis frame align.	450.00	-
4	Rear rim balance.	80.00	-
5	Workmanship.	400.00	150.00
	Total Labour Amount	1,200.00	150.00
	Total Parts and Labour	4,836.68	1,724.28

Our Reference : FTA/III/2106/19416

Your Reference: MCV2021D0000280

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)	\$ 4,350.00	\$ 1,350.00

REMARKS :

Our recommended Lump Sum Repair Cost is **\$1,350.00** (instead of the submitted repair cost of **\$4,350.00** .In normal circumstances, repairs to the vehicle would take approximately **04 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FORMTEAM ADJUSTERS PTE LTD** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FORMTEAM ADJUSTERS PTE LTD

Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser

Bryan Teng
Automobile Appraiser