

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

Hp 96699986

INVOICE

Ms Sylvia Patama

Invoice No : PA/2102/0012/tpw
Our Ref : PA/FBR2951/0121/tpw
Date : 17 February 2021

Claim Type	Third Party	Date of Accident	16 January 2021
Vehicle No.	FBR 2951 Z	Date of Inspection	25 January 2021
No	Description	Amount (S\$)	
1	Survey fees inclusive of Transportation and Photographs (62) copies	\$482.00	
Total			\$482.00
Singapore Dollar: Four Hundred And Eighty-Two Only			
All payments made payable to : Prudent Adjustors Services			


Prudent Adjustors Services
Bok Jee Tan

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Ms Sylvia Patama

Our Ref : PA/FBR2951/0121/tpw

Date : 17 February 2021

REFERENCES

Claim Type	: Third Party	Date of Accident	: 16 January 2021
Vehicle No.	: FBR 2951 Z	Date of Assignment	: 25 January 2021
Make	: Yamaha	Date of Inspection	: 25 January 2021
Model	: AEROX GDR155A CVT ABS	Date of Re-inspection	: 29 Jan & 01 Feb 2021
Reg. Date	: 06 April 2020	COE Expiry	: 05 April 2030
Color	: Black	Chassis No	: MH3SG4640LJ071085
Odometer	: 3,120 km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	IRC	110/80-14	5mm
Rear	IRC	140/70-14	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at rear, frontal and left side.
Please refer to photographs and assessment of repairs for details
Enclosed (62) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$5,969.57 Revised Assessment \$4,350.00 Lump sum

Survey conducted at Revology Bikes Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Seven (7) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICESVehicle No: **FBR 2951 Z**

Our Ref : PA/FBR2951/0121/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Cover handle upper	1 pc	Usable	165.00	~
2	Handle bar complete	1 pc	Bent	120.00	120.00
3	Handle bar balancer (end grips)	1 set	Cut	60.00	60.00
4	Wind mirror	1 set	Grazed	120.00	120.00
5	Brake lever LH	1 pc	Grazed /bent	48.00	48.00
6	Front centre panel	1 pc	Usable	145.00	~
7	Headlamp cowling LH/RH @ 167.50/-	2 pcs	Cut LH	335.00	167.50
8	Headlamp assy (LED)	1 pc	Hdr cracked	685.00	685.00
9	Front signal @ \$86/-	2 pcs	Scratch LH	172.00	86.00
10	Front fork @ \$410/-	2 pcs	Bent	820.00	820.00
11	Front mudguard	1 pc	Cut	110.00	110.00
12	Foot board LH	1 pc	Cut	186.50	186.50
13	Footrest board lower side cover @ \$128.60/-	2 pcs	Cut LH	257.20	128.60
14	Rear mudguard	1 pc	Deformed	158.60	158.60
15	Crankcase cover	1 pc	Cut	285.00	285.00
16	Muffler protector	1 pc	Cracked	110.00	110.00
				3,777.30	3,085.20
List price less 10%				377.73	308.52
				3,399.57	2,776.68
<u>Add special nett item</u>					
17	ERP IU unit	1 pc	Grazed/cut	160.00	160.00
18	Steering cone bearing	1 set	Necessary	180.00	120.00
19	Body sticker	1 set	Necessary	180.00	150.00
20	Rear box	1 pc	Grazed	350.00	280.00
21	Rear box rack with base	1 set	Broken/bent	180.00	150.00
				1,050.00	860.00
<u>Labour</u>					
Towing (2 trips)				150.00	120.00
Steering stem repair & align				200.00	150.00
Chassis frame align				550.00	450.00
Rear rim balance				120.00	80.00
Workmanship				500.00	400.00
				1,520.00	1,200.00
Total parts & labour concluded				5,969.57	4,836.68
Lump sum repair adjustment (less 10% due to no used parts)					<u>4,350.00</u>

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBR 2951 Z**

Our Ref : PA/FBR2951/0121/tpw

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan