

## COMFORT TRANSPORTATION PTE LTD

**REPAIR ESTIMATE**

Vehicle No. : SHC8152G

Date: 10/10/2022

Make : HYUNDAI

Insurance: INCOME

Model : I-40

MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <del>202</del> X Repair			\$ 553.00
1	REAR BUMPER CLIPS <del>102</del>			\$ 22.00
1	REAR BUMPER LOWER COVER <del>102</del> CAP			\$ 228.00
1	REAR BUMPER REINFORCEMENT <del>102</del> NN			\$ 428.40
SUB TOTAL				\$ 1,231.40
LESS 20%				\$ 246.28
DISCOUNTED TOTAL				\$ 985.12
RENEW ADVERTISEMENT STICKER <del>102</del> MC				\$ 250.00
				\$ 250.00
Labour Charge				
PANEL BEATING				\$ 300.00
SPRAY PAINTING CHARGE				\$ 300.00
REMOVE/REFIX REVERSE SENSOR				\$ 60.00
TOTAL LABOUR				\$ 660.00
ESTIMATE TOTAL				\$ 1,895.12

Nett

280  
250  
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.  
4/5  
6no Arg  
10/10  
2pm

-20%: 800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices on "without prejudice" basis
- Third party survey on "without prejudice" basis
- No illegal practices
- Supplemental survey to be surveyed and is subject to the insurance company

Acknowledged by:

Signature:

Date: