

ASIS REC BY: Tauji


REF: CS/MSG 22010129/Try 3.

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD (TP) / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8116K.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS wp^ PRs
Date: _____ Person Contacted: _____
Vehicle: IN / OUT



Veh No: SMG5128S Yr Regn: 2018 / Dec.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: BMW 2161 Gran Tourer C.C. 1499
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 175092 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBAGV12070 ED 05531
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 205/55R17
R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / Pir / SUMI /
TOYO / YOKO or _____
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 13/10/22
Survey held at Benz Body Works
Des. of Damages (Ft) (Rear) / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Range: \$15,000 - \$17,000, 14 days.

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?

2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. invs (\$ _____)

Survey Fee:	
Transportation:	
S + RS. \$:	
Photos	
Others	

Rep. Form: _____
Date/Time, File Return to?