

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHD4184K

Make : HYUNDAI

Model : IONIQ(G3)

Date: 11.10.2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / <i>CRA</i>			\$459.40 ✓
10	REAR BUMPER CLIPS / <i>all</i>			\$22.00 ✓
1	REAR BUMPER CENTRE MOULDING ASSY / <i>el</i>			\$451.25 ✓
1	REAR BUMPER REINFORCEMENT ✓ <i>CRA</i>			\$394.80 ✓
1	REAR BUMPER REINFORCEMENT BRACKET LH RH X <i>NN</i>		\$138.10	\$276.20
2	REAR BUMPER SIDE BRACKET LH RH X <i>NN</i>		\$55.80	\$111.60
1	BOOTLID X <i>Repair</i>			\$2,549.70
1	BOOTLID HYUNDAI PLATE / <i>all</i>			\$24.30 ✓
1	EMBLEM HYBRID / <i>all</i>			\$24.30 ✓
1	EMBLEM - IONIQ / <i>all</i>			\$31.30 ✓
1	REAR BUMPER TOWING COVER X <i>NN</i>			\$98.80 ✓
1	REAR BUMPER FOG LAMP ✓ <i>BR</i>			\$201.50 ✓
1	ANTENNA ASSY SMARTK ✓ <i>NW</i>			\$40.50 ✓
SUB TOTAL				\$4,685.65
LESS 20%				\$937.13
DISCOUNTED TOTAL				\$3,748.52
	REAR NUMBER PLATE WITH TRIM COVER / <i>BT</i>			\$55.00
	BOOTLID COMFORT TEL NO STICKER / <i>all</i>			\$40.00
	BOOTLID COMFORT LOGO STICKER / <i>all</i>			\$30.00
	BOOTLID COMFORT APP STICKER / <i>all</i>			\$30.00
	REAR BUMPER REVERSE SENSOR / <i>cut</i>			\$180.00
NETT				\$335.00
Labour Charge				
	PANEL BEATING			\$750.00
	SPRAY PAINTING CHARGE			\$600.00
	CHK ALL LIGHTING			\$60.00
	REMOVE/ REFIX BOOT LID GLASS			\$120.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
TOTAL LABOUR				\$1,670.00
ESTIMATE TOTAL				\$5,753.52

## Labour Charge

PANEL BEATING

SPRAY PAINTING CHARGE

CHK ALL LIGHTING

REMOVE/ REFIX BOOT LID GLASS

TUFF KOTE

REMOVE/REFIX REVERSE SENSOR

4 Days.

4/5 Gms. 11/10/22

LKK Auto Consultants hence notify

the Repairer of the following:

• To surveyor of the following:

• Parts of the survey

• No of the survey

• No of the survey

• No of the survey

• No of the survey

• No of the survey

• No of the survey

• No of the survey

• No of the survey

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

-20%: 2300