

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

TP INSURER:
NIL

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

Claimant Insurer:

AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	22/AL/TP-213(10)
Policy No:		Date of Loss:	11/10/2022
Vehicle Reg. No.:	SLH8235C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TEO HSIN WEI		
Make/Model:	SUZUKI SWIFT, 1.4 (A)	Vehicle Reg. Date:	21/11/2016
Vehicle Colour:	WHITE	Chassis No:	JSAFZC82S00333729
Engine No:	K14B1135785		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	7,001.50
Miscellaneous Items	755.00
Labour	3,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,956.50
+ GST 7.00% (S\$)	766.96
Nett Amount (S\$)	11,723.46

This claim is handled by: WEN YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

not Audited
here
19/10/22
2/5 @ 5900
take photo after repair
1 day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2022)
Parts: 143 SUZUKI SWIFT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH8235C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Dis</i>	0.00	0.00	*560.00 F <i>/</i>
2	2		*REAR BUMPER RETAINER <i>But</i>	0.00	0.00	*50.00 F <i>/</i>
3	10		*REAR BUMPER CLIPS <i>Rec</i>	0.00	0.00	*25.00 F <i>/</i>
4	1		*REAR BUMPER REINFORCEMENT <i>MT</i>	0.00	0.00	*225.00 F <i>X</i>
5	1		*REAR END PANEL <i>Body</i>	0.00	0.00	*350.00 F <i>/</i>
6	1		*REAR END PANEL TOP GARNISH <i>Tr</i>	0.00	0.00	*225.00 F <i>/</i>
7	6		*TOP GARNISH CLIPS <i>11</i>	0.00	0.00	*15.00 F <i>X</i>
8	2		*REAR TAIL LAMP <i>CM</i>	0.00	0.00	*480.00 F <i>/</i>
9	1		*FRT GRILLE <i>CR</i>	0.00	0.00	*75.00 F <i>/</i>
10	1		*GRILLE CENTRE LOGO <i>SCN</i>	0.00	0.00	*25.00 F <i>/</i>
11	4		*GRILLE CLIPS <i>11</i>	0.00	0.00	*10.00 F <i>X</i>
12	1		*FRT BUMPER <i>Torn</i>	0.00	0.00	*480.00 F <i>/</i>
13	2		*FRT BUMPER RETAINER <i>But</i>	0.00	0.00	*50.00 F <i>/</i>
14	10		*FRT BUMPER CLIPS <i>Rec</i>	0.00	0.00	*25.00 F <i>/</i>
15	1		*FRT BUMPER TOW COVER <i>M. 1</i>	0.00	0.00	*20.00 F <i>/</i>
16	1		*FRT BUMPER LOWER GRILLE <i>Torn</i>	0.00	0.00	*85.00 F <i>/</i>
17	1		*FRT BUMPER REINFORCEMENT (TOP) <i>But</i>	0.00	0.00	*365.00 F <i>2</i>
18	1		*FRT BUMPER REINFORCEMENT GARNISH (TOP) <i>Dis</i>	0.00	0.00	*230.00 F <i>2</i>
19	1		*AIRCON CONDENSER <i>Part / But</i>	0.00	0.00	*585.00 F <i>2</i>
20	1		*RADIATOR <i>11</i>	0.00	0.00	*750.00 F <i>X</i>
21	2		*HEADLAMP <i>CNA</i>	0.00	0.00	*900.00 F <i>3</i>
22	1		*CENTRE TOP PANEL <i>But</i>	0.00	0.00	*150.00 F <i>2</i>
23	2		*HEADLAMP PANEL <i>11</i>	0.00	0.00	*150.00 F <i>X</i>
24	1		*FRT BONNET <i>MT/But</i>	0.00	0.00	*535.00 F <i>/</i>
Sub Total (S\$)						6,365.00
+ Margin on L,N Items 10.00% (S\$)						636.50
Total Parts (S\$)						7,001.50

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRT NUMBER PLATE	CU	40.00	✓
2	1	RADIATOR COOLANT	new	25.00	✓
3	1	REAR NUMBER PLATE	BERP	40.00	✓
4	1	REVERSE CAMERA	11	400.00	X
5	1	REVERSE SENSOR	smk	250.00	200

Sub Total (\$\$) 755.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	WIRE CHECKING	New	30.00	✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	✓
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60
4	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	150.00	60
5	LABOUR (REAR)	New	700.00	✓
6	LABOUR (FRONT)	New	700.00	400
7	SPRAY PAINTING (REAR)	New	700.00	600
8	SPRAY PAINTING (FRT)	New	700.00	500

Gross Labour Cost (\$\$) 3,200.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P-5215
+ 108
5736.50
305
2450
8491.50
302
8794