

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 03 Aug 2023

**Preliminary Advice**

Vehicle No	: XE5826R	Accident Date	: 07/10/2022
Make	: MITSUBISHI FUSO	Policy No.	: DMCVSNW00099622200
Assignment Date	: 18/10/2022	Excess	: S\$3,000.00
Date of Inspection	: 12/10/2022	Est. Duration of Repair	: 15
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,186.69	(Estimate \$41,770.54 + Supplementary \$15,416.15)
Revised Amount	:S\$	54,186.69	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	54,186.69	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	171,000.00
COE / PARF Rebate	:S\$	18,923.00
Salvage Value	:S\$	
Margin for Repair	:S\$	152,077.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY